

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0909/2021/JT
DATE : 8-Nov-21
WIP : 52150

Xiao Tony .
\$16878.28.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 9/11/21
YOUR INSURED VEH NO : SKE 4315 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SARAVANAN S/O GOVINDASAMY
ADDRESS : BLK 509 WEST COAST DRIVE
#09-289
SINGAPORE 120509
TELEPHONE : HP +65 98525309
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SD21V01454/VPC/R00
VEHICLE NO : **SGZ 9359 L**
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 29/12/2020
ENGINE NO : DEM 025429
CHASSIS NO : WAUZZZF40MN000954
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 4-Nov-21
PLACE OF ACCIDENT : 16 CLEMENTI ROAD
JUNCTION OF U-TRUN

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6341 1183

EMAIL : NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGZ 9359 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$ 360.00	✓ ✓
2	TO RENEW REAR WINDSCREEN AND LHS 1/4 GLSS TO FACILITATE FENDER RENEWAL.	S/N \$ 600.00	✓ ✓
3	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN AND LHS SIDE 1/4 GLASS.	S/N \$ 400.00	✓ 180.00
4	TO CARRY OUT WARE SEEPAGE TEST ON 1/4 GLASS.	S/N \$ 200.00	150 ✓
5	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 1,400.00	300 ✓
6	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS, LUGGAGE COMPARTMENTS TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRRAG, ETC	S/N \$ 1,400.00	✓ ✓
SUB-TOTAL LABOUR CHARGES		: \$ 4,360.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6365 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SGZ 9359 L

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
7	TO RENEW LHS REAR WHEEL SUSPENSION ASSY WITH SUBFRAME.	S/N \$ 2,400.00	X
8	TO DISMANTL AND RENEW REAR BUMPER. TO CUT OUT AND WELD LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	\$ 4,900.00	3000 ✓
9	TO RESPRAY REAR BUMPER,. TO CUT OUT WELD LHS REAR FEDNER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,500.00	45 x 550 = 2475 ✓
10	TO RENEW LHS REAR RIM. TO CARRY OUT PRE/POST WHEEL ALIGNMENT.	S/N \$ 520.00	240 ✓
11	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 16,872.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 9359 L

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	REAR BUMPER <i>Repair</i>	1	\$ 2,342.00	+	
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 166.00	+	
3	REAR BUMPER TOP GUIDE SECTION - LH / RH <i>new</i>	2	\$ 46.00	+	
4	REAR BUMPER GUIDE SECTION - LH	1	\$ 44.00	+	
5	REAR SECTIONAL PARTS - LH <i>Dented</i>	1	\$ 4,052.00	✓	3,241.60
6	REAR WINDSCREEN <i>? new</i>	1	\$ 1,154.00	✓	923.20
7	REAR 1/4 GLASS	1	\$ 656.00	✓	524.40
8	PRIMER <i>new</i>	2	\$ 40.00	✓	31.52
9	REAR WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 240.00	+	
10	REAR SUB FRAME <i>new</i>	1	\$ 3,286.00	X	
11	REAR WISHBONE - LOWER	1	\$ 859.00	?X	
12	REAR WISHBONE - LH UPPER	1	\$ 556.00	?X	
13	REAR WISHBONE - LH FRONT	1	\$ 123.00	?X	
14	REAR WISHBONE - LH REAR	1	\$ 447.00	?X	
15	REAR TRACK ROD - LH REAR	1	\$ 171.00	?X	
16	REAR WHEEL BEARING HOUSING - LH <i>new</i>	1	\$ 990.00	X	
17	REAR WHEEL BEARING - LH <i>new</i>	1	\$ 654.00	?X	
18	STONE CHIP GUARD <i>new</i>	1	\$ 45.00	4X	
19	REAR ABSORBER - LH <i>? new</i>	1	\$ 301.00	?X	
20	REAR COUPLING ROD <i>? new</i>	1	\$ 86.00	?X	
SUB TOTAL SPARE PARTS			\$ 16,258.00		

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SGZ 9359 L

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR ANTI ROLL BAR <i>NEC</i>	1	\$ 412.00	7X
22	1/4 GLASS <i>NEC</i>	S/N	\$ 100.00	✓
23	CRYLIC SEALANT	S/N	\$ 180.00	✓
24	GRAVITY WAX	S/N	\$ 140.00	✓
25	STONE CHIP TREATMENT <i>NEC</i>	S/N	\$ 180.00	✓
26	METAL FILLER POWER	S/N	\$ 280.00	✓
27	REAR WINDSCREEN SEALANT <i>NEC</i>	S/N	\$ 200.00	✓
28	REAR RIM - LH <i>lit</i>		TBC	700.00
29	REAR TYRE RIM - LH <i>lit</i>		TBC	340.00
30	SUNDRIES <i>NEC</i>	\$	350.00	40.56
TOTAL SPARE PARTS		:	\$ 18,100.00	
TOTAL LABOUR CHARGES		:	\$ 16,872.00	
GRAND TOTAL		:	\$ 34,972.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian King
SURVEYED DATE : 09/11/21
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorized, 13 days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: