

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD158M**AAD2111-019***Not Notarised*
L1 By Q2450/h

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Make:

Date of Accident :

Third Party Insurer :

Date of Registration :

05 NOV 2021**SHD158M**

VF1ABL15AUC282265

RENAULT

LATITUDE

02/11/2021

III

04/09/2015

PART**LIST**

- 1 BUMPER COVER FRT
- 1 BUMPER ABSORBER FRT
- 1 BUMPER BEAM FRT
- 1 BUMPER BRACKET KIT FRT RH
- 1 HEADLAMP RH
- 1 WIPER RESERVOIR
- 1 FENDER PANEL FRT RH
- 1 WHEELARCH FRT RH

\$	<i>Bu</i>	747.20	✓
\$	<i>Pl</i>	394.68	X
\$	<i>R</i>	663.70	X
\$	<i>D.V</i>	101.40	✓
\$	<i>MRM</i>	743.60	✓
\$	<i>SL</i>	179.60	X
\$	<i>B</i>	437.10	✓
\$	<i>Tn</i>	191.40	✓
\$		3,458.68	
10% \$		345.87	
\$		3,112.81	

Special Nett

- 1SET BUMPER BRACKET CTR CLIP
- 1SET BUMPER BRACKET SIDE CLIP RH RR
- 1SET BUMPER RETAINER RH CLIP RR
- 1SET BUMPER BRACKET SIDE CLIP LH RR
- 1SET BUMPER RETAINER CLIP LH RR
- 1 BUMPER CLIP FRT
- 1 FENDER CLIP
- 1 FENDER LINER CLIP

\$	<i>na</i>	33.00	X
\$	<i>na</i>	10.00	X
\$	<i>na</i>	20.00	X
\$	<i>na</i>	10.00	X
\$	<i>na</i>	20.00	X
\$	<i>na</i>	85.00	<i>665m</i>
\$	<i>na</i>	65.00	X
\$	<i>na</i>	60.00	✓
TOTAL \$		303.00	
TOTAL PARTS \$		3,415.81	

LABOUR

Putty And Spray Painting Of The Affected Portion.

\$ 3,000.00 *4401*

Trans-cab Auto Services Pte Ltd**AAD2111-019**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD158M

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	3,000.00	400/
To Rust-Proofing Of The Affected Areas.	\$	170.00	30/
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	nn 170.00	X
To repair and realign rear exhaust pipe.	\$	nn 170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	nn 170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	nn 170.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	nn 170.00	X
To check steering geometry and computer wheel alignment	\$	220.00	60/
To Check Electrical Lighting Concerned.	\$	170.00	20/

TOTAL \$ 7,580.00**Over All Total \$ 14,108.62****(LUMP SUM)****Repair Days****10 DAYS**
*2 days***LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: