

ASS. REC. BY: Tan Jiah REF: CC4/ALG21011321/T1e93.

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TR / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SHC16411 Yr Regn: 2017, July  
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Toyota Prius c.c. 1798  
 Colour: Blue A/C: Insured / Std / NI / NA  
 Sp. Reading \_\_\_\_\_ T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: JDKCB3FU503562621  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Brake: Inorder / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/65R15  
 R: na


BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or Westlake  

Front	Rear
R/Bal. <u>6</u> mm	R/Bal. <u>6</u> mm
L/Bal. <u>6</u> mm	L/Bal. <u>6</u> mm
D.O.A. _____	D.O.I. <u>5/11/21</u>

 Survey held at Comfort Lodge  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or \_\_\_\_\_

The U/C / Chassis frame / Body Structure affected due to collision.

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: WP Chiang  
 Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>Battery weak</u>

Date/Time, File Pass to?  : Prell. Report  
 : Final Report  
 Date/Time, File Return to?

Days Of Repair: \_\_\_\_\_  
 Resurvey No. of Trip: \_\_\_\_\_

1) \_\_\_\_\_  
 2) \_\_\_\_\_  
 Report Format : \_\_\_\_\_  
 Lump Sum / I.B.L. (\$) \_\_\_\_\_

Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	_____
Transportation:	_____
\$ + RS	_____
Photos	_____
Others	_____
TOTAL	_____

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE\*

DATE 03/11/21 04:20 PM

CHIANG/AIG

VEHICLE NO SHC1641H

MAKE REG .26/07 /2017

MODEL TOYOTA PRIUS G4A

Qty	Parts Description/ Labour	Type	Unit Price	Amount
				<del>458.60</del> \$458.60
1	REAR BUMPER			del \$552.60
1	REAR BUMPER LOWER COVER			? \$318.80
1	REAR BUMPER REINFORCEMENT			X \$232.60
1	REAR BUMPER UNDER SIDE COVER RH			del \$82.70
1	REAR BUMPER TOW COVER			X \$112.70
1	REAR BUMPER SIDE RETAINER LH/RH			del \$22.00
10	REAR BUMPER CLIP			
	<b>SUB TOTAL</b>			<b>\$1,780.00</b>
	25.00%			\$445.00
	<b>DISCOUNTED TOTAL</b>			<b>\$1,335.00</b>
1	BUMPER MAT			X \$50.00
1	BUMPER ADVERTISEMENT			del \$50.00
1	BUMPER REVERSE SENSOR			? \$135.70
				<b>\$235.70</b>
	<b>Labour Charge</b>			
	Panel Beating		350	\$500.00
	Spray Painting Charge		250	\$300.00
	Tuff Kote		X	\$60.00
	Towing Fee		? <i>towing receipt</i>	\$60.00
	Remove/Refix Reverse Sensor		30	\$60.00
	<b>TOTAL LABOUR</b>			<b>\$980.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$2,550.70</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

*Tanpin 97495749*  
*wp' 5/11/21 @ 5pm*  
*02 days*  
*cls during after repair*  
*tanpin@lkkauto.com*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Modification(s) is allowed
- Any modification(s) must be resurveyed and approved by Insurance Company

Acknowledged by Repairer

**JOB CARD Sales Order:**

Item: ARC Repair TP(CLSO)1  
Customer: COMFORT TRANSPORTATION PTE LTD  
Customer No. 7010045  
Address 383 SIN MING DRIVE  
Singapore SINGAPORE 575717  
(R) 65508755 (O)  
(P)


REGN NO.: <b>SHC1641H</b>	MILEAGE
MAKE: <b>TOYOTA</b>	FUEL E.....1/2.....F
MODEL <b>PRIUS HYBRID(G4)03.</b>	DATE/TIME IN <b>11.2021 16:20</b>
YR OF MANU. <b>26.07.2017</b>	TARGET DATE
CHASSIS CODE <b>JTDKB3FU503562621</b>	COMPLETION DATE/TIME:

QUANTITY CARD NO.

JOB DESCRIPTION

Accident Date: 03.11.2021  
Nature: 3P 03.11.2021

NO LABOR CODE DESCRIPTION



BOOKED & PASSED OUT BY: \_\_\_\_\_

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Signature/Date  
Name of Service Advisor  
To be kept by Security Guard

Exit Pass  
Vehicle No.: **SHC1641H**  
Date

Returned to Service Reception upon collection