

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
(Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Asher.

Vehicle Number : **SMV7329G**
Vehicle Model : **HONDA CRV**
Accident Date : **05.11.2021**
Original Reg Date : **07.12.2020**

Date : **08.11.2021**
Chassis : **MRHRW1880MP000006**
TP INS. **CHINA TAIPIING**

ESTIMATE

1	1 pc	Tailgate <i>Distorted</i>		1,138.50	✓
2	1 pc	Tailgate Badge <i>New</i>		98.60	✓
3	1 pc	Tailgate Emblem "CRV" <i>New</i>		95.30	✓
4	1 pc	Tailgate Emblem "vtec" <i>New</i>		94.60	✓
5	1 pc	Tailgate Outer Chrome Moulding <i>cracked</i>		398.50	✓
6	1 set	Tailgate Outer Chrome Moulding Clips <i>New</i>		30.00	10. ✓
7	2 pcs	Tailgate Number Plate Lamps <i>New</i>	49.00	98.00	+
8	1 pc	Tailgate Opener Switch <i>New</i>		138.20	+
9	1 pc	Tailgate number plate outside garnish <i>New</i>		298.00	+
10	1 pc	Tailgate Outer Handle <i>New</i>		185.00	+
11	1 set	Tailgate Bottom Garnish Clips <i>New</i>		40.00	+
12	1 pc	Tailgate Pocket Handle <i>New</i>		46.00	+
13	1 pc	Tailgate auto close detect sensor <i>cracked</i>		485.60	✓
14	2 pcs	Tailgate Stopper <i>New</i>	18.00	36.00	+
15	1 pc	Tailgate Inner Trim <i>cracked</i>		398.60	✓
16	1 set	Tailgate Inner Trim Clips <i>New</i>		30.00	✓
17	1 pc	Tailgate Inner Lock <i>Damaged</i>		285.30	✓
18	1 pc	Tailgate latch <i>New</i>		48.50	+
19	2 pc	Tailgate lamp <i>RH cracked</i>	711.30	1,422.60	711.30 478
20	2 pc	Tailgate lamp inner sealer <i>New</i>	38.00	76.00	+
21	1 pc	Tailgate Lock Catch <i>New</i>		46.20	+
22	1 pc	Tailgate Weatherstrip <i>New</i>		183.50	+
23	2 pcs	Tailgate Hinges <i>2 New</i>	65.00	130.00	+
24	2 pcs	Tailgate Absorber <i>New</i>	685.90	1,371.80	+
25	1 pc	Tailgate Windscreen Inner Seal <i>New</i>		85.00	✓
26	1 pc	Tailgate Windscreen molding <i>New</i>		185.60	✓
27	1 pc	Rear Bumper <i>Distorted</i>		582.30	✓
28	2 pcs	Rear Bumper Side Retainers <i>RH Damaged</i>	85.30	170.60	35
29	1 set	Rear Bumper Clips <i>New</i>		50.00	30. ✓
30	1 pc	Rear Bumper Center garnish <i>New</i>		154.60	+
31	1 pc	Rear Bumper reinforcement <i>Dented</i>		458.90	355
32	1 pc	Rear Bumper Side garnish <i>RH Distorted</i>	198.60	397.20	198.60
	1 pc	Rear Bumper Side chrome trim <i>New</i>		125.60	65
	1 pc	Rear Bumper mudflap <i>Damaged</i>		75.80	✓
33	1 pc	Rear Bumper Reflectors <i>RH smashed</i>		175.80	✓

34	4 pcs	Rear Bumper sensors <i>2 pieces damaged</i>	245.60	982.40	<i>491.20</i>
35	4 pcs	Rear Bumper sensors holder <i>new</i>	45.20	180.80	<i>✓</i>
36	2 pcs	Rear Bumper Reflectors Bracket <i>new</i>	63.00	126.00	<i>x</i>
37	1 pc	Rear Bumper foot detect tailgate open sensor <i>new</i>		548.30	<i>x</i>
38	1 pc	Rear Bumper Under Cover <i>torn</i>		195.00	<i>✓</i>
39	1 set	Rear Bumper Under Cover Clips <i>new</i>		30.00	<i>✓</i>
40	1 pc	Rear corner bumper <i>Distorted</i>		305.20	<i>✓</i>
41	1 pc	End Panel (Outer) <i>Distorted</i>		656.00	<i>✓</i>
42	1 pc	End Panel (Inner) <i>Repair</i>		395.00	<i>+</i>
43	1 pc	End Panel Top Trim <i>cracked</i>		175.30	<i>✓</i>
44	1 set	End Panel Top Trim Clips <i>new</i>		30.00	<i>10.</i>
45	1 pc	End Panel smart key sensor <i>new</i>		156.30	<i>x</i>
46	1 pc	Spare Tyre Top Board <i>new</i>		425.00	<i>x</i>
47	1 pc	Spare Tyre panel <i>new</i>		685.90	<i>x</i>
48	1 pc	Taillamps <i>cracked</i>		785.30	<i>545.</i>
49	1 pc	Taillamps panel <i>Repair</i>		385.90	<i>x</i>
50	1 pc	Taillamp Inner Sealer <i>Not New</i>	38.00	76.00	<i>x</i>
51	2 set	Taillamps Clips <i>new</i>	25.00	50.00	<i>10.</i>
52	2 pcs	Rear Fender Inner Trims <i>3 NP</i>	345.80	691.60	<i>+</i>
53	2 set	Rear Fender Inner Trim Clips <i>new</i>	30.00	60.00	<i>+</i>
54	1 pc	Rear Fender air duct <i>Deformed</i>		85.60	<i>✓</i>
55	1 pc	Rear Fender <i>Distorted</i>		788.90	<i>✓</i>
56	1 pc	Rear Fender arch garnish <i>cracked</i>		185.30	<i>✓</i>
57	1 pc	Rear Exhaust Silencer <i>Bent.</i>		1,985.60	<i>1255</i>
58	4 pcs	Rear Exhaust Mountings <i>1 piece torn</i>	65.80	263.20	<i>35.</i>
59	1 pc	Rear Exhaust Gasket <i>new</i>		85.30	<i>45.</i>

4204

10314.40

19,970.10

Less 20%

3,994.02

8251.52

subtotal

15,976.08

Special Nett

1	1 pc	Rear Windscreen Sealant <i>new</i>		60.00	<i>✓</i>
2	1 pc	Rear Number Plate with Cover <i>new</i>		70.00	<i>+</i>
3	1 pc	Reverse Camera <i>new</i>		380.00	<i>x</i>
4	1 set	Body Panel Joint Sealant <i>new</i>		120.00	<i>60</i>
5	2 pc	Rear Exhaust Chrome Pipe <i>RH Dmgd</i>	180.00	360.00	<i>100.</i>

220

Labour charge

Panel Beating		2,200.00	1200.
Spray painting		2,000.00	850
Check Wiring on tailamp		120.00	30.
Anti rust		100.00	60.
Remove and install rear windscreen.		120.00	✓
Remove and install tailgate parts.		120.00	80.
Remove and install carpet and seat.		120.00	60.
Remove and install reverse sensor.		90.00	50
Remove and install reverse camera.		150.00	50
Remove and install rear exhaust.		120.00	✓ 80.
		\$ 22,106.08	

2480

Adrian King.
w/s 08/11/21.
09 Days.

total: 10951.52

2/s: 8.7K.

8.7K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____