



Case Details

Case Reference Number : TAX/11/21/2005
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4566Y

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-16570-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : EQ Insurance Company Ltd
 Accident Date and Time : 03/11/2021 06:25 AM
 Vehicle Age(In Months) : 49

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FR BUMPER	1	495.50	495.50	25.00	371.63	Replace	1	371.63	Replace	See ✓
One Time Key In	Main			ABSORBER, FR BUMPER	1	70.30	70.30	25.00	52.72	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			COVER ASSY, ENGINE UNDER CENTER SET	1	452.80	452.80	25.00	339.60	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			COVER, ENGINE UNDER SIDE RH	1	76.90	76.90	25.00	57.68	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			LAMP ASSY, FOG, RH	1	910.20	910.20	10.00	819.18	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			UNIT, HEADLAMP, LH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			UNIT, HEADLAMP, RH	1	2,558.90	2,558.90	10.00	2,303.01	Replace	0	0.00	Check	B?
One Time Key In	Main			GRILLE, RADIATOR	1	165.00	165.00	25.00	123.75	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			GRILLE SUB-ASSY	1	335.60	335.60	25.00	251.70	Replace	0	0.00	Not Give	Xan

Total Spare Part Cost 36,399.89

Surveyor Total 3,581.39

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 29,119.91

Final Sur Total 2,865.11

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace ▾	rec ✓
One Time Key In	Main			HINGE ASSY, HOOD, RH	1	57.00	57.00	25.00	42.75	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			MOULDING RH	1	83.30	83.30	25.00	62.47	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			CLIP, WINDSHIELD , RH & LH , NO.1	2	8.80	17.60	25.00	13.20	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			FENDER SUB-ASSY, FR , RH	1	933.10	933.10	25.00	699.83	Replace	1	699.83	Replace ▾	bu ✓
One Time Key In	Main			LINER, FR FENDER, RH	1	198.40	198.40	25.00	148.80	Replace	0	0.00	Check ▾	?
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			SHAFT ASSY, FRONT DRIVE , RH	1	1,295.70	1,295.70	25.00	971.78	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			DISC, BRAKE FRONT	1	416.30	416.30	25.00	312.23	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			WHEEL ASSY, STEERING	1	2,880.20	2,880.20	25.00	2,160.15	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			END SET, TIE ROD, RH	1	155.90	155.90	25.00	116.93	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			LOWER ARM SUB-ASSY, FRONT RH	1	631.60	631.60	25.00	473.70	Replace	0	0.00	Not Give ▾	Xan
One Time Key In	Main			WHEEL, DISC FRONT	1	1,555.10	1,555.10	25.00	1,166.32	Replace	1	1,166.32	Replace ▾	ca ✓

Total Spare Part Cost 36,399.89

Lump Sum Discount (%) 20.00

Final Spare Part Cost 29,119.91

Surveyor Total 3,581.39

Lump Sum Dis (%) 20.00

Final Sur Total 2,865.11

SMRT Recommendation											Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace		
One Time Key In	Main			TYRE	1	126.74	126.74	0.00	126.74	Replace	1	126.74	Replace	cut ✓	
One Time Key In	Main			KNUCKLE, STEERING, LH	1	555.20	555.20	25.00	416.40	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			DISC, BRAKE FRONT	1	416.30	416.30	25.00	312.23	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			ABSORBER SET, SHOCK, FRONT LH	1	398.10	398.10	25.00	298.58	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			LOWER ARM SUB-ASSY, FRONT LH	1	631.60	631.60	25.00	473.70	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	X11	
One Time Key In	Main			PANEL SUB-ASSY, REAR DOOR , RH	1	1,243.90	1,243.90	25.00	932.93	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			SUPPORT, FR BUMPER RH	1	76.90	76.90	25.00	57.68	Replace	0	0.00	Check	?	
One Time Key In	Main			COVER, ENGINE UNDER SIDE LH	1	76.90	76.90	25.00	57.68	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			HOOD SUB-ASSY	1	938.40	938.40	25.00	703.80	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			CLIP, WINDSHIELD , RH & LH , NO.3	2	9.10	18.20	25.00	13.65	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			MOULDING ASSY, BODY ROCKER PANEL , RH	1	576.00	576.00	25.00	432.00	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			JOINT ASSY, LWR BALL , RH & LH	1	200.10	200.10	25.00	150.07	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			ABSORBER SET, SHOCK, FRONT RH	1	398.10	398.10	25.00	298.58	Replace	0	0.00	Not Give	X11	
One Time Key In	Main			BAR, STABILIZER, FR	1	356.00	356.00	25.00	267.00	Replace	0	0.00	Not Give	X11	

Total Spare Part Cost 36,399.89

Surveyor Total 3,581.39

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 29,119.91

Final Sur Total 2,865.11

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, FRONT FLOOR UNDER , LH	1	425.50	425.50	25.00	319.13	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			COVER ASSY, CENTER FLOOR UNDER , LH	1	390.20	390.20	25.00	292.65	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			SHAFT ASSY, FRONT DRIVE , LH	1	1,175.10	1,175.10	25.00	881.32	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			MEMBER SUB-ASSY, FR LH	1	1,959.50	1,959.50	25.00	1,469.63	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			COVER, OUTER MIRROR, LH	1	89.50	89.50	25.00	67.13	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			STICKER DECAL SMRT (DOOR)	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	na ✓
One Time Key In	Main			SUPPORT, FR BUMPER LH	1	82.30	82.30	25.00	61.72	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			COVER, ENGINE UNDER, REAR	1	36.50	36.50	25.00	27.38	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			LAMP ASSY, FOG, LH	1	910.20	910.20	10.00	819.18	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			PIXEL STICKER	1	60.00	60.00	0.00	60.00	Replace	1	60.00	Replace	na ✓
One Time Key In	Main			HINGE ASSY, HOOD, LH	1	57.00	57.00	25.00	42.75	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			WINDSCREEN FRONT GLASS SUB-ASSY	1	1,626.40	1,626.40	25.00	1,219.80	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	0.00	111.00	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			WINDSCREEN FRONT DAM, WINDOW GLASS	1	44.00	44.00	25.00	33.00	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			WINDSCREEN FRONT MOULDING, TOP FRONT	1	44.00	44.00	25.00	33.00	Replace	0	0.00	Not Give	Xan

Total Spare Part Cost 36,399.89

Lump Sum Discount (%) 20.00

Final Spare Part Cost 29,119.91

Surveyor Total 3,581.39

Lump Sum Dis (%) 20.00

Final Sur Total 2,865.11

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING LH	1	83.30	83.30	25.00	62.47	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			CLIP, WINDSHIELD , RH & LH , NO.2	2	8.80	17.60	25.00	13.20	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	1	39.67	Replace	Free
One Time Key In	Main			PAD, FR WHEEL RH	1	57.70	57.70	25.00	43.28	Replace	0	0.00	Not Give	inx
One Time Key In	Main			SEAL SUB-ASSY, RH	1	50.20	50.20	25.00	37.65	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			PROTECTOR, FR FENDER RH	1	90.40	90.40	25.00	67.80	Replace	0	0.00	Check	E?
One Time Key In	Main			APRON SUB-ASSY, FRONT FENDER , RH	1	944.20	944.20	25.00	708.15	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	554.20	554.20	25.00	415.65	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			COVER, FRONT FLOOR UNDER , RH	1	427.30	427.30	25.00	320.48	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			KNUCKLE, STEERING, RH	1	555.20	555.20	25.00	416.40	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			JOINT ASSY, LWR BALL , RH & LH	1	200.10	200.10	25.00	150.07	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			MEMBER SUB-ASSY, FR RH	1	2,012.70	2,012.70	25.00	1,509.53	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			GEAR ASSY, STEERING	1	1,620.70	1,620.70	25.00	1,215.53	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			LINK ASSY, FRONT STABILIZER , RH & LH	1	196.70	196.70	25.00	147.52	Replace	0	0.00	Not Give	Xan
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , RH	1	1,373.50	1,373.50	10.00	1,236.15	Replace	0	0.00	Not Give	Xan

Total Spare Part Cost 36,399.89

Surveyor Total 3,581.39

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 29,119.91

Final Sur Total 2,865.11

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, OUTER MIRROR, RH	1	89.50	89.50	25.00	67.13	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			FENDER SUB-ASSY, FR , LH	1	933.10	933.10	25.00	699.83	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			EMBLEM, SIDE PANEL (HYBRID)	1	52.90	52.90	25.00	39.67	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			LINER, FR FENDER, LH	1	194.30	194.30	25.00	145.73	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			PAD, FR WHEEL LH	1	57.70	57.70	25.00	43.28	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			HUB & BEARING ASSY, RH & LH	1	554.20	554.20	25.00	415.65	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			COVER, FRONT FLOOR UNDER , LH	1	425.50	425.50	25.00	319.13	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			END SET, TIE ROD, LH	1	155.90	155.90	25.00	116.93	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			LINK ASSY, FRONT STABILIZER , RH & LH	1	196.70	196.70	25.00	147.52	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			MIRROR ASSY, OUTER REAR VIEW , LH	1	1,283.90	1,283.90	10.00	1,155.51	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			PANEL SUB-ASSY, FRONT DOOR RH	1	1,249.60	1,249.60	25.00	937.20	Replace	1	937.20	Replace	See ✓
One Time Key In	Main			CHECK ASSY, FRONT DOOR	1	153.50	153.50	25.00	115.13	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			HINGE ASSY, FRONT DOOR , UPPER RH	1	82.10	82.10	25.00	61.57	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			HINGE ASSY, FRONT DOOR , LOWER RH	1	92.10	92.10	25.00	69.07	Replace	0	0.00	Not Give	Xnn
One Time Key In	Main			DOOR FRONT WINDOW REGULATOR SUB-ASSY, RH	1	230.80	230.80	25.00	173.10	Replace	0	0.00	Not Give	Xnn

Total Spare Part Cost 36,399.89

Surveyor Total 3,581.39

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 29,119.91

Final Sur Total 2,865.11

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			DOOR FRONT MOTOR ASSY, POWER WINDOW REGULATOR , RH	1	768.60	768.60	10.00	691.74	Replace	0	0.00	Not Give	Xny
One Time Key In	Main			LOCK ASSY, FRONT DOOR RH	1	581.90	581.90	25.00	436.42	Replace	0	0.00	Not Give	Xny
One Time Key In	Main			DOOR LOCK STRIKER	1	38.00	38.00	25.00	28.50	Replace	0	0.00	Not Give	Xny
Total Spare Part Cost									36,399.89	Surveyor Total		3,581.39		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20.00		
Final Spare Part Cost									29,119.91	Final Sur Total		2,865.11		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR FRONT RH PORTION	507.00	500.00	
2	Main	TO REPAIR FRONT LH PORTION	338.00	0.00	Xny
Total:			845.00	500.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200.00	
2	Main	TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00	Xm
3	Main	TO REPSRAY FRONT HOOD	378.00	0.00	Xm
4	Main	TO RESPRAY FRONT FENDER RH	378.00	200.00	
5	Main	TO RESPRAY RIM	360.00	0.00	Xny
6	Main	TO RESPRAY APRON PANEL RH	180.00	0.00	Xny
7	Main	TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00	Xny
8	Main	TO RESPRAY FRT MEMBER LH	180.00	0.00	Xny
Total:			3,888.00	600.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
9	Main	TO RESPRAY FRT MEMBER,RH	180.00	0.00 Xnn	
10	Main	TO RESPRAY FRONT FENDER LH	378.00	0.00 Xnn	
11	Main	TO RESPRAY FRONT DOOR RH	378.00	200.00	
12	Main	TO RESPRAY REAR DOOR RH	378.00	0.00 Xnn	
13	Main	RESPRAY MIRROR COVER LH	180.00	0.00 Xnn	
14	Main	RESPRAY MIRROR COVER RH	180.00	0.00 Xnn	
Total:			3,888.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TRANSFER DOOR MECHANISM	120.00	60.00	
2	Main	TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	60.00	
3	Main	TO REMOVE AND REFIX WING MIRROR	240.00	0.00 Xnn	
4	Main	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	240.00	30.00	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	450.00	0.00 Xnn	
6	Main	TO REMOVE AND REFIX UNDERCARRIAGE	120.00	0.00 Xnn	
7	Main	TO REPLACE SUNDRY PARTS	100.00	0.00 Xnn	
8	Main	TO CHECK & RESET SYSTEM FUNCTION	80.00	40.00	
9	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 Xnn	
10	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00	
11	Main	TO WASH AND VACUUM	60.00	0.00 Xnn	
12	Main	TOWING CHARGE	56.00	0.00 Xnn	
Total:			1,766.00	230.00	

Summary

Estimator Assessment(\$)

Surveyor Assessment(\$)

01, 3:03 PM

https://vacsweb.smrt.com.sg/Estimation.aspx

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	29,119.91	2,865.11
Total Labour Cost	845.00	500.00
Total Spray Painting	3,888.00	600.00
Other	1,766.00	230.00
Overall Total	35,618.91	4,195.11
Lump Sum Repair Option	☐	☒
Lump Sum Total	35,600.00	4,200.00
Surveyor Approved Amount		4,200.00
No of Repair Days*	9	6
Remarks	-	RESURVEY AFTER REPAIR / LUMP SUM
Surveyor Name		Rasul
Signature		
Survey Date	08/11/2021	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	05/11/2021 09:23 (SGT)
Date of Accident	03/11/2021 14:25 (SGT)
Exact Location of Accident	Near S'goon Sports Cplx, Singapore
Additional Location Information	YIO CHU KANG LINK TOWARDS BOUNDARY ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4566Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	STRIDES TAXI PTE LTD
Company Reg No	1XXXXX369K
Email Address	Auto-Svcs-TARC@smrt.com.sg
Mobile Phone No	(Phone) +65-68662671
Alternative Phone No	(Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Prius
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1798

INSURANCE COMPANY

Name of Insurance Company	MS First Capital Insurance Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	D-21097466MFSH
Cover Note Number	-

DRIVER

Name of Driver	LIM TIAN HOCK
NRIC No	SXXXX393G

Date Of Birth	19/02/1951
Occupation	Outdoor
Date Of Driving Pass	16/01/1970
Driving experience	51 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-68662672
Alt. Phone Number	-
Email Address	Auto-Svcs-TARC@smrt.com.sg
Address	1
Address complement	-
Postcode	-
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	UNKNOWN
Gender	Male

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

I WAS TRAVELLING STRAIGHT ALONG YIO CHU KANG LINK AT THE LEFT MOST LANE WITH A PASSENGER ON BOARD. SUDDENLY A LORRY GBG7380X FROM MY RIGHT LANE CUT TOWARDS MY LANE, I TRIED TO AVOID AND SWERVED TO THE LEFT, WHICH SUBSEQUENTLY CAUSED MY TAXI HIT ONTO THE KERB ON THE LEFT. THEREAFTER MY TAXI RETURN BACK TO THE LANE. AT THAT JUNCTURE, THE LORRY KEEP CUTTING INTO MY LANE AND RESULTED A COLLISION BETWEEN THE RIGHT FRONT PORTION OF MY TAXI WITH THE LEFT PORTION OF THE LORRY.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBG7380X
Vehicle Manufacturer	-
Vehicle Model	-

Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
NRIC No
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
-
Commercial vehicle
NG CHUAN HAO
SXXXX009C
-
-
BLK 966 HOUGANG AVE 9
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

SERANGGON
STADIUM



YIO CHU KANG LINK

A-54045614
B-6557320X

Describe Circumstances of the Accident

the Accident

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date &
Time

Driver's Signature (If driver is not the policyholder) / Date
& Time: July 16, 2008

Witnessed by Reporting Centre
Personnel

W

Pl 3/11/20

Signature (If driver is not the police officer):
3/11/21 16-50WS

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHC4566Y
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZR5098599
Chassis No.:	JTDKB3FUX03573033
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Oct 2017
First Registration Date:	12 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2025
PARF Rebate Amount:	\$3,750.00
COE Expiry Date:	11 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$16,694.00
Total Rebate Amount:	\$20,444.00

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Nov 2021

OK