



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|--|--|--------------------|
| LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555 | | Ref: CS/LPC21011325/Etf3e2 Date: 18/03/2022 Code: LPC2 | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | XD 9511C | Veh. Inspected | SBS 6744Y |
| Policy No. | Z/21/VC00/112085 | Coverage (\$) | 0.00 |
| Claim No. | 21/21/21/VC00/025120 | Excess (\$) | 0.00 |
| Assign From | GERALD POH | Assign Date | 08/11/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | MERCEDES BENZ CITARO | c.c | 7700 |
| Engine No. | HIDDEN | Year of Reg. | 2014 |
| Chassis No. | WEB62808323125361 | Colour | MULTI COLOUR |
| Odometer | 670390 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | STANDARD ALLOY RIM |
| General | FAIR | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 295/80 R22.5 | BRIDGESTONE | 4 mm |
| L/H Front Tyre | 295/80 R22.5 | BRIDGESTONE | 4 mm |
| R/H Rear Tyre | 295/80 R22.5 (D) | BRIDGESTONE | 4/4 mm |
| L/H Rear Tyre | 295/80 R22.5 (D) | BRIDGESTONE | 4/4 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 04/11/2021 | Inspection Date | 08/11/2021 |
| Survey held at | SBS TRANSIT LTD (Branch) 28 SOON LEE ROAD SINGAPORE 628083 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 10 Working Days | |