



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909			Ref: CS/UOI21011330/R1vf3e2	
			Date: 26/11/2021	
			Code: UOI2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SMT 5990A	
	Policy No. DHOM120061492100	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	750.00	
	Assign From JOSEPHINE WONG	Assign Date	08/11/2021	
2. Vehicle Particulars & Condition				
	Make & Model AUDI A1 SB 1.0 TFSI (PI)	c.c	999	
	Engine No. HIDDEN	Year of Reg.	2015	
	Chassis No. WAUZZZ8X0FB031147	Colour	RED	
	Odometer 79840 KM	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General FAIR			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm
	L/H Front Tyre	205/50 R16	BRIDGESTONE	6 mm
	R/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm
	L/H Rear Tyre	205/50 R16	BRIDGESTONE	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date 05/11/2021	Inspection Date	08/11/2021	
	Survey held at CYS AUTOMOBILE SERVICES PTE LTD 38 WOODLANDS INDUSTRIAL PARK EAST 1 #07-17 ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700			
5a. Remarks				
	A)THE MARKET VALUE IS S\$44,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	