

ASSIGNED BY: ked

## ASSIGNMENT

From

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

88587896

Yr Regn:

23 Sep 2009

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

SCANIA KUB 4X2 cc 9290

Colour:

Multicolor

A/C:

Insured / Std / NI / NA

Sp Reading

890482.6

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

YS2K 4X20001-865670

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

225/70R225

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

28-11-21

Survey held at

W/S

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

3pm

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

No fix provided  
GIAComplete estimate give later

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Misc. (\$)

Survey Fee:

Transportation:

3 + RS \$

Photos

Other:

Total:

Report Format:

Equip. Used / Modified:

## Soon Bee Vehicle & Bodywork Maintenance

10 Anson Road #33-17 International Plaza Singapore 079903.

Tel: 90036715 Fax: 62256130 Email: soonbee\_vehicle@yahoo.com.sg

GST Registration No: 53076555A

Our Ref No. : SB-19504

Date: 02-Nov-21

AMK Workshop.

Foreman: Li Ming

FAX: 64562752

### QUOTATION FOR ACCIDENT REPAIR ON BUS NO:

**LKK Auto Consultants** hence notify  
the Repairer of the following:







- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: SBS8789G

Date:

We are pleased to offer our best proposal to provide our services of labour for repair of above mentioned vehicle at SBS Transit, Ang Mo Kio Workshop.

1)	Vehicle No : Model :	SBS8789G SD												
2)	Total Cost :	<table><tr><td>- Material &amp; Parts Cost</td><td>:</td><td></td></tr><tr><td>- Labour Cost</td><td>:</td><td>\$ 850.00 ✓</td></tr><tr><td>GST (7%) :</td><td></td><td>\$ 59.50</td></tr><tr><td>Total :</td><td></td><td>\$ 909.50</td></tr></table>	- Material & Parts Cost	:		- Labour Cost	:	\$ 850.00 ✓	GST (7%) :		\$ 59.50	Total :		\$ 909.50
- Material & Parts Cost	:													
- Labour Cost	:	\$ 850.00 ✓												
GST (7%) :		\$ 59.50												
Total :		\$ 909.50												
	Work Scopes	<p>Dismantle and replace rear bumper assy Dismantle and replace rear engine access door Repair o/s/r lighting panel Repair n/s/r lighting panel Dismantle and replace n/s/r tail light 3pcs Repair n/s/r dome panel Touch up putty on accident area Respray accident area</p> <div></div> <p>Supply workers for 22 ManHour</p> <p>TERM OF PAYMENT: 30 DAYS UPON DELIVERY OF VEHICLES Vehicle Electric and wiring system not included</p> <p>(B) Materials and Parts: - Supply by SBS Transit</p> <p>(C) Mechanical/Engine Effect - NA</p> <p>2 Days</p>												

**Note: Quotation valid for 1 Month only**

This is a computer-generated document. No signature will be required.