

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/MSG21011335/UVF3E2

**Date:** 18/11/2021

### REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A29142301AT2  
Claimant Vehicle No : SJR7040A Insured Vehicle No : SMK712S  
Date of Loss: 05/11/2021 Nature of Claim: TP Claim No: 638717

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJR7040A**  
Make & Model: HONDA JAZZ, 1.3 L (A) Engine No: L13Z11009538  
Reg. Date: 09/07/2009 (Man. Year: 2008) Chassis No: JHMGE68509S209534  
Colour: Yellow Odometer: 154646 km  
Engine Capacity: 1339 cc  
Market Value/New Car Price: N/A  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/50 R16 Rear Tyre Size: 195/50 R16  
Front Left Side: Kumho 6 mm Rear Left Side: APLUS 6 mm  
Front Right Side: Kumho 6 mm Rear Right Side: APLUS 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,460.80	3,174.32	5,286.48	62.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,820.00	2,460.00	2,360.00	48.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,280.80</b>	<b>5,634.32</b>	<b>7,646.48</b>	<b>57.58</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,500.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,280.80</b>	<b>4,500.00</b>	<b>8,780.80</b>	<b>66.12</b>

### INSPECTION

Date of Assignment: 08/11/2021  
Date Inspected: 08/11/2021 Inspected At: Zoom Autowerkz Pte Ltd (HQ)  
Blk 15 Kaki Bukit Road 4, #01-53 Bartley Biz Centre  
Singapore 417808  
Estimated Period of Repair: 7.0 days

**Adjuster:** MARCUS CHUA

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 15 Nov 2021)
<b>Parts:</b> 144	HONDA JAZZ 1.3 L (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SJR7040A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	62.90 FL	*62.90 FL
2	1		*REAR TAILGATE	Dented	762.20 FL	*762.20 FL
3	2		*REAR TAILGATE DAMPERS	Not Necessary	219.00 FL	*- FL
4	1		*REAR TAILGATE INNER LOCK	Jammed / Twisted	168.50 FL	*168.50 FL
5	1		*REAR TAILGATE INNER TRIM BOARD	Deformed / Cracked	194.40 FL	*194.40 FL
6	1		*REAR TAILGATE LOGO	Not Necessary	22.50 FL	*- FL
7	1		*REAR TAILGATE OUTER GARNISH	Not Necessary	112.30 FL	*- FL
8	1		*REAR TAILGATE RUBBER	Serviceable	89.80 FL	*- FL
9	1		*REAR TAILGATE JAZZ EMBLEM	Necessary	28.80 FL	*28.80 FL
10	1		*REAR TAILLAMPS	N/S Cracked /O/S Not Necessary	674.00 FL	*285.20 FL
11	1		*REAR END PANEL	Repair	296.60 FL	*- FL
12	1		*REAR END PANEL INNER GARNISH	Not Necessary	58.40 FL	*- FL
13	1		*REAR BUMPER	Deformed / Torn	520.80 FL	*466.20 FL
14	2		*REAR BUMPER SIDE RETAINERS	Necessary	37.20 FL	*37.20 FL
15	1		*REAR SPARE TYRE BOARD	Not Necessary	179.70 FL	*- FL
16	1		*REAR SPARE TYRE PANEL	Repair	737.00 FL	*- FL
17	1		*REAR EXHAUST SILENCER	Not Necessary	462.40 FL	*- FL
18	2		*REAR EXHAUST MOUNTINGS	Not Necessary	57.00 FL	*- FL
19	1		*FRONT BONNET	Not Necessary	516.90 FL	*- FL
20	1		*FRONT BONNET LOCK	Not Necessary	115.30 FL	*- FL
21	2		*FRONT HEADLAMPS	Not Necessary	1,171.20 FL	*- FL
22	1		*FRONT GRILLE	Not Necessary	137.50 FL	*- FL
23	1		*FRONT GRILLE LOGO	Not Necessary	34.70 FL	*- FL
24	1		*FRONT BUMPER	Repair	560.90 FL	*- FL
25	2		*FRONT BUMPER FOG LAMPS	Not Necessary	570.00 FL	*- FL
26	1		*FRONT BUMPER REINFORCEMENT	Repair	282.20 FL	*- FL
27	2		*FRONT BUMPER SIDE RETAINERS	Not Necessary	53.80 FL	*- FL
28	1		*FRONT WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
29	1		*SET REAR BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
30	1		*REAR BUMPER LOWER SPOILER	Cracked	650.00 FS	*650.00 FS
31	1		*REAR NUMBER PLATE	Not Necessary	50.00 FS	*- FS
32	1		*SET REAR REVERSE SENSOR	Shorted	380.00 FS	*200.00 FS
33	1		*SET FRONT BUMPER CLIP	Not Necessary	60.00 FS	*- FS
34	1		*FRONT BUMPER LOWER SPOILER	Cracked	650.00 FS	*650.00 FS
35	1		*FRONT NUMBER PLATE	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>10,086.00</b>	<b>3,575.40</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$)</b>	1,625.20	401.08
<b>Total Parts (\$)</b>	<b>8,460.80</b>	<b>3,174.32</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND RESET HEADLAMPS FOCUSING }	New	80.00	30.00
2	TO REMOVE, REPLACED DAMAGED LAMPS AND CHECK UP REAR WIRING }	New	80.00	0.00
3	TO REMOVE AND REFIT INNER GARNISHES	New	150.00	60.00
4	TO REMOVE AND REFIT REAR REVERSE SENSOR	New	150.00	50.00
5	TO TRANSFER REAR TAILGATE MECHANISM AND WIRING ASSEMBLY	New	80.00	60.00
6	TO REMOVE AND REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
7	TO REMOVE, REFIT AND REPLACE EXHAUST SILENCER AND MOUNTINGS	New	120.00	0.00
8	TO APPLY UNDERCOATING	New	180.00	40.00
9	PANEL BEATING	New	1,800.00	600.00
10	TO RE-SPRAY PAINTING ON THE AFFECTED AREAS	New	2,000.00	1,500.00
			<b>Gross Labour Cost (S\$)</b>	<b>4,820.00</b>
				<b>2,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >