



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

Not Authorised

11 November 2021

*dele
 8/11/21
 2/5# 4500/
 2 days.*

REG NO.: SJR 7040 A
 MAKE/MODEL: HONDA JAZZ

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	LIST ITEMS	
1	Rear windshield moulding <i>NEU</i>	\$ 62.90 /
1	Rear tailgate <i>DD</i>	\$ 762.20 /
2	Rear tailgate dampers <i>11</i>	\$ 219.00 X
1	Rear tailgate inner lock <i>11/11/1</i>	\$ 168.50 /
1	Rear tailgate inner trim board <i>2e/cnx</i>	\$ 194.40 /
1	Rear tailgate logo <i>11</i>	\$ 22.50 X
1	Rear tailgate outer garnish <i>11</i>	\$ 112.30 X
1	Rear tailgate rubber <i>SVC</i>	\$ 89.80 X
1	Rear tailgate "JAZZ" emblem <i>NEU</i>	\$ 28.80 /
2	Rear taillamps <i>N/scre 015nn 28420</i>	\$ 674.00 <i>IPC</i>
1	Rear end panel <i>R</i>	\$ 296.60 X
1	Rear end panel inner garnish <i>11</i>	\$ 58.40 X
1	Rear bumper <i>Del to.1 466.20</i>	\$ 520.80 /
2	Rear bumper side retainers <i>NEU</i>	\$ 37.20 /
1	Rear spare tyre board <i>11</i>	\$ 179.70 X
1	Rear spare tyre panel <i>R</i>	\$ 737.00 X
1	Rear exhaust silencer <i>11</i>	\$ 462.40 X
2	Rear exhaust mountings <i>11</i>	\$ 57.00 X
1	Front bonnet <i>11</i>	\$ 516.90 X
1	Front bonnet lock <i>11</i>	\$ 115.30 X
2	Front headlamps <i>11</i>	\$ 1,171.20 X
1	Front grille <i>11</i>	\$ 137.50 X
1	Front grille logo <i>11</i>	\$ 34.70 X
1	Front bumper <i>R</i>	\$ 560.90 X
2	Front bumper fog lamps <i>11</i>	\$ 570.00 X
1	Front bumper reinforcement <i>R</i>	\$ 282.20 X
2	Front bumper side retainers <i>11</i>	\$ 53.80 X
		\$ 8,126.00
	Less 20%	\$ 1,625.20
		\$ 6,500.80

<u>SPECIAL NETT ITEMS</u>			
1	Rear windscreen sealant	na	\$ 60.00 40
1	Rear bumper clip (1 set)	na	\$ 60.00 30
1	Rear bumper lower spoiler	na	\$ 650.00 ✓
1	Rear number plate	na	\$ 50.00 X
1	Rear reverse sensor (1 set)	Stroked	\$ 380.00 200
1	Front bumper clip (1 set)	na	\$ 60.00 ✓
1	Front bumper lower spoiler	na	\$ 650.00 ✓
1	Front number plate	na	\$ 50.00 X
			<hr/>
			\$ 1,960.00

<u>S/N</u>	<u>LABOUR CHARGES</u>		
1	To check wiring and reset headlamps focusing.		\$ 80.00
2	To remove, replaced damaged lamps and check up rear wiring.		\$ 80.00 } 30
3	To remove and refit inner garnishes.		\$ 150.00 60
4	To remove and refit rear reverse sensor.		\$ 150.00 50
5	To transfer rear tailgate mechanism and wiring assembly.		\$ 80.00 60
6	To remove and refit rear windscreen glass.		\$ 180.00 120
7	To remove, refit and replace exhaust silencer and mountings.	na	\$ 120.00 X
8	To apply undercoating.		\$ 180.00 40
9	Panel beating.		\$ 1,800.00 600
10	To re-spray painting on the affected areas.		\$ 2,000.00 1,500
			<hr/>
			\$ 4,820.00

GRAND TOTAL :

\$ 13,280.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-20254
203
P-160432
S.N-1570.00
L-2460
563432
293
4507