



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
 #08-1339 Singapore 470130
 Tel: 9450 7920
 * zoomautowerks@gmail.com

Not Authorized
del
8/11/21
2/5 \$4500
7 days

11 November 2021

REG NO.: SJR 7040 A
 MAKE/MODEL: HONDA JAZZ

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
<u>LIST ITEMS</u>		
1	Rear windscreen moulding <i>NEU</i>	\$ 62.90 /
1	Rear tailgate <i>DD</i>	\$ 762.20 /
2	Rear tailgate dampers <i>11</i>	\$ 219.00 X
1	Rear tailgate inner lock <i>1m/7w1</i>	\$ 168.50 /
1	Rear tailgate inner trim board <i>Del/cru</i>	\$ 194.40 /
1	Rear tailgate logo <i>11</i>	\$ 22.50 X
1	Rear tailgate outer garnish <i>11</i>	\$ 112.30 X
1	Rear tailgate rubber <i>SVC</i>	\$ 89.80 X
1	Rear tailgate "JAZZ" emblem <i>NEU</i>	\$ 28.80 ✓
2	Rear taillamps <i>n/scre 015nn 284.20</i>	\$ 674.00 <i>120</i>
1	Rear end panel <i>R</i>	\$ 296.60 X
1	Rear end panel inner garnish <i>11</i>	\$ 58.40 X
1	Rear bumper <i>Del to n 466.20</i>	\$ 520.80 /
2	Rear bumper side retainers <i>NEU</i>	\$ 37.20 /
1	Rear spare tyre board <i>11</i>	\$ 179.70 X
1	Rear spare tyre panel <i>R</i>	\$ 737.00 X
1	Rear exhaust silencer <i>11</i>	\$ 462.40 X
2	Rear exhaust mountings <i>11</i>	\$ 57.00 X
1	Front bonnet <i>11</i>	\$ 516.90 X
1	Front bonnet lock <i>11</i>	\$ 115.30 X
2	Front headlamps <i>11</i>	\$ 1,171.20 X
1	Front grille <i>11</i>	\$ 137.50 X
1	Front grille logo <i>11</i>	\$ 34.70 X
1	Front bumper <i>R</i>	\$ 560.90 X
2	Front bumper fog lamps <i>11</i>	\$ 570.00 X
1	Front bumper reinforcement <i>R</i>	\$ 282.20 X
2	Front bumper side retainers <i>11</i>	\$ 53.80 X
		\$ 8,126.00
	Less 20%	\$ 1,625.20
		\$ 6,500.80

SPECIAL NETT ITEMS

1	Rear windscreen sealant	neu	\$	60.00	40
1	Rear bumper clip (1 set)	neu	\$	60.00	30
1	Rear bumper lower spoiler	neu	\$	650.00	✓
1	Rear number plate	neu	\$	50.00	X
1	Rear reverse sensor (1 set)	Shoked	\$	380.00	200
1	Front bumper clip (1 set)	neu	\$	60.00	X
1	Front bumper lower spoiler	neu	\$	650.00	✓
1	Front number plate	neu	\$	50.00	X
			\$	<u>1,960.00</u>	

S/N

LABOUR CHARGES

1	To check wiring and reset headlamps focusing.		\$	80.00	
2	To remove, replaced damaged lamps and check up rear wiring.		\$	80.00	330
3	To remove and refit inner garnishes.		\$	150.00	60
4	To remove and refit rear reverse sensor.		\$	150.00	50
5	To transfer rear tailgate mechanism and wiring assembly.		\$	80.00	60
6	To remove and refit rear windscreen glass.		\$	180.00	120
7	To remove, refit and replace exhaust silencer and mountings.	neu	\$	120.00	X
8	To apply undercoating.		\$	180.00	40
9	Panel beating.		\$	1,800.00	600
10	To re-spray painting on the affected areas.		\$	2,000.00	1500
			\$	<u>4,820.00</u>	

GRAND TOTAL :

\$ 13,280.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-20254
202
P-160432
S.N-1570.00
L-2460
563432
293
0507