

AUTO PTE LTD
 @ KAKI BUKIT #01-49 SINGAPORE 415875
 4457
 65 64524584
 g No: 201929175W

Vehicle number: SKU230L
 Make and model: Honda Vezel
 Chassis: RU1-1021656

Qty	Spare parts	List price	2015
1	Tailgate	\$ 800.00	953.30 DDV
1	Tailgate "Vezel" emblem	\$	✓ 56.50 NECV
1	Tailgate windscreen glasss upper rubber moulding	\$	✓ 52.00
1	Tailgate windscreen glass lower rubber moulding	\$	✓ 52.00 } NECV
1	Tailgate windscreen glasss RH rubber moulding	\$	✓ 52.00
1	Tailgate windscreen glass LH rubber moulding	\$	✓ 52.00
1	Tailgate LH lamp	\$ 335.00	413.30 BRV
1	Tailgate LH lamp gasket	\$	✓ 38.50 NECV
1	Tailgate RH lamp	\$ 335.00	413.30 BRV
1	Tailgate RH lamp gasket	\$	✓ 38.50 NECV
1	Tailgate outer garnish	\$	✓ 231.00 BRV
1	Tailgate outer garnish emblem	\$	✓ 28.00 NECV
1	Tailgate RH number plate lamp	\$	55.10 } NDX
1	Tailgate LH number plate lamp	\$	55.10 }
1	Tailgate reverse camera	\$	1,020.70 NDX
1	Tailgate inner trim board	\$	✓ 154.70 BRV
1	Tailgate lock	\$ 180.20	189.00 JMV
1	Tailgate lock catch	\$	27.50 NDX
1	Tailgate inner pull handle	\$	28.60 NDX
1	Tailgate RH damper	\$	182.00 } NDX
1	Tailgate LH damper	\$	182.00 }
1	Tailgate weatherstrip	\$	✓ 96.80 TNV
1	Rear bumper	\$	✓ 465.70 BRV
1	Rear bumper lower cover	\$ 129.00	250.00 BRV
1	Rear bumper LH reflector	\$ 75.00	141.10 BRV
1	Rear bumper LH side cover	\$	✓ 198.00 BRV
1	Rear bumper LH side retainer	\$	✓ 26.50 } NECV
1	Rear bumper RH side retainer	\$	✓ 26.50 }
1	LH taillamp	\$ 385.00	487.60 BRV
1	LH taillamp gasket	\$ 20.00	44.20 NECV
1	RH taillamp	\$ 385.00	487.60 BRV
1	RH taillamp gasket	\$ 20.00	44.20 NECV
1	End panel	\$ 382.70	415.60 DDV
1	End panel inner garnish	\$	✓ 109.00 BRV
1	End panel antenna sensor	\$	✓ 65.10 } BRV
1	End panel buzzer sensor	\$	✓ 85.60 }
1	Rear compartment panel tray garnish	\$ 201.00	485.90 BRV
1	Rear compartment panel tray garnish top cover board	\$	430.30 NDX

2015

1	Rear LH fender 2	\$	✓	884.80	DDV
1	Rear LH fender arch moulding	\$	✓	198.00	BRV
1	Rear LH fender splash shield	\$		145.90	NDX
1	Rear LH fender inner trim board	\$	✓	298.50	BRV
1	Rear LH fender air vent	\$		45.30	NDV
1	Rear RH fender 2	\$	884.80 ✓	884.80	BRV
1	Rear RH fender arch moulding	\$	✓	198.00	
1	Rear RH fender splash shield	\$		145.90	NDX
1	Rear LH fender inner trim board	\$	✓	298.50	BRV
1	Rear RH fender air vent	\$	✓	45.30	BRV
1	Bonnet	\$		892.30	NDX
1	Bonnet RH hinge	\$		48.50	
1	Bonnet LH hinge	\$		48.50	NDX
1	Bonnet lock	\$		98.00	NDX
1	Bonnet RH inner side rubber moulding	\$		37.50	
1	Bonnet LH inner side rubber moulding	\$		37.50	
1	Bonnet RH inner centre rubber moulding	\$		23.00	
1	Bonnet LH inner centre rubber moulding	\$		23.00	NDX
1	Bonnet insulator	\$		122.30	
1	Front bumper	\$	762.70	801.70	BRV
1	Front bumper RH side retainer	\$	✓	22.80	NEC
1	Front bumper LH side retainer	\$	✓	22.80	
1	Front bumper RH fog lamp 2 HH	\$	308.90	327.70	BRV
1	Front bumper RH fog lamp bracket	\$		27.00	NSX
1	Front bumper RH fog lamp garnish HH	\$		✓46.00	BRV
1	Front bumper LH fog lamp HH	\$	308.90	327.70	BRV
1	Front bumper LH fog lamp bracket	\$		27.00	NDX
1	Front bumper LH fog lamp garnish	\$		✓46.00	BRV
1	Front bumper lower centre grille	\$		✓78.40	BRV
1	Front bumper lower spoiler	\$	279.00	381.00	BRV
1	Front bumper reinforcement	\$	274.70	321.00	PDV
1	Front bumper reinforcement RH top moulding	\$		38.00	
1	Front bumper reinforcement LH top moulding	\$		38.00	NDX
1	Front bumper towing cover	\$		17.10	NDX
1	Front grille	\$	250.00	351.80	BRV
1	Front grille emblem	\$		✓23.40	NEC
1	Front grille centre bracket	\$	39.50	78.00	BRV
2	Front grille chrome moulding	\$	153.80	196.00	BRV
1	Front grille outer cover	\$		421.00	BRV
1	RH headlamp assy	\$	194.70	1,795.50	BRV
1	RH head				

1	Radiator	\$	1,376.60	} NDX
1	Radiator RH side guide	\$	31.80	
1	Radiator LH side guide	\$	31.80	
1	Aircon condenser	\$	568.30	
1	Air duct	\$	127.80	

\$	23,441.40
-20% \$	4,688.28
\$	18,753.12

Qty Spare parts

Special nett price

1set	Bonnet insulator clips	\$	100.00	NNX
1set	Front bumper clips	\$	30.00	100.00 NEC
1set	Front RH fender splash shield clips	\$		80.00 NNX
1set	Front RH fender arch moulding clips	\$		80.00 NNX
1set	Front LH fender splash shield clips	\$		80.00 NNX
1set	Front LH fender arch moulding clips	\$		80.00 NNX
1set	Front grille clips	\$	30.00	70.00 NEC
1	Radiator coolant	\$		90.00 NNX
1	Front number plate	\$	30.00	70.00 BR
1	Tailgate windscreen glass sealant	\$	30.00	80.00 } NEC
1	Tailgate windscreen glass inner seal	\$	40.00	50.00 } NEC
1set	Tailgate inner trim board clips	\$	30.00	80.00 NEC
1set	Tailgate outer garnish clips	\$	30.00	70.00 NEC
1set	Rear bumper clips	\$	30.00	100.00 NEC
1set	Rear bumper reverse sensors	\$	200.00	320.00 SC
1set	Rear fender RH arch moulding clips	\$	30.00	80.00 } NEC
1set	Rear fender LH arch moulding clips	\$	30.00	80.00 } NEC
1	Rear fender RH sealant	\$	30.00	80.00 } NEC
1set	Rear fender RH inner trim board clips	\$	30.00	80.00 } NEC
1set	Rear fender LH inner trim board clips	\$	30.00	80.00 } NEC
1	Rear fender LH sealant	\$		80.00 } NNX
1	Rear number plate	\$		70.00 } NNX
1	End panel	\$		70.00 NNX
1set	End panel inner garnish clips	\$	30.00	50.00 NEC

(FRONT PORTION)

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

	\$	400.00	1,000.00
Spray painting on affected panels	\$	400.00	900.00
Check wiring and lighting system	\$		70.00 NNX
Apply rust coating chemical on affected panels	\$		40.00 NNX
Remove and replace aircon			

Refocus and adjust headlamps assy

\$ ~~60.00~~ NNX

(RERR PORTION)

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 1000.00 ~~1,600.00~~ ✓

Spray painting on affected panels

\$ ~~1400.00~~ 1,400.00

Check wiring and lighting system

\$ ~~100.00~~ NNX

Apply rust coating chemical on affected panels

\$ ~~80.00~~ NNX

Remove and replace tailgate windscreen glass to assist repair

\$ 120.00 ~~250.00~~ ✓

Remove and replace tailgate inner components to assist repair

\$ 80.00 ~~180.00~~ ✓

Remove and replace tailgate reverse camera to assist repair

\$ ~~100.00~~ NNX

Remove and replace rear bumper reverse sensors to assist repair

\$ ~~60.00~~ 100.00 ✓

Remove and replace rear inner trims, garnish and boards to assist repair

\$ ~~80.00~~ 220.00 ✓

Remove and reinstall petrol tank, pipes and hoses to sensors to assist repair

\$ ~~150.00~~ NNX

Remove and reinstall roof lining, seats and carpet to assist repair

\$ ~~380.00~~ NNX

Survey

Resurvey

8/11/2021

9/11/2021

TGumlin

TGumlin

1430hrs

1630 hrs

Total: \$ 28,003.12

Lump sum repair

Repair days 10

Parts 13484.80

SJ 1190.00

Labour 3140.00

17814.80

@ 20% 3562.96

14,251.84

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Supplementary

Vehicle No: SKU230L
Model and make: Honda Vezel

Qty Parts

List price 2015

1	RH rear door inner trim board	RM	\$	355.00	650.40	BRV
1	RH rear door lock	RM	\$	196.30	✓ 196.30	JMV
1	LH rear door inner trim board	RM	\$	355.00	650.30	BRV
1	LH rear door lock	RM	\$	196.30	✓ 196.30	JMV
1	Rear bumper lower cover		\$	RPT X	251.00	BRV
1	Rear compartment tool sponge tray		\$	✓	226.40	BRV
1	Exhaust silencer	R	\$	517.70	700.20	DDV
1	Exhaust silencer gasket	RM	\$	40.50	✓ 40.50	NEV

\$ 2,911.40
-20% \$ 582.28
\$ 2,329.12

Qty Parts

Special nett price

1set	RH rear door inner trim board clips	RM	\$	30.00	60.00	NEV
1set	LH rear door inner trim board clips	RM	\$	30.00	60.00	NEV
1	Rear bumper chrome step moulding		\$	250.00	380.00	DD
1	End panel chrome moulding		\$	✓	250.00	DDV

Labour

Remove and replace exhaust silencer and gasket to assist repair \$ -120.00 NNT

Final amount: \$ 3,199.12

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resurvey
9/11/2022
Termin
16/30/15