> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID: Vehicle Details	540D
Vehicle No.:	SKU230L
Vehicle to be Exported:	Yes
Intended Deregistration Date:	20 Apr 2022
Vehicle Make:	HONDA
Vehicle Model:	VEZEL 1.5S AUTO
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	L15B3521673
Chassis No.:	RU11021656
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$19,463.00
Original Registration Date:	29 Jun 2015
First Registration Date:	29 Jun 2015
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$9,463.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	28 Jun 2025
PARF Rebate Amount: Intended COE Rebate Details	\$6,150.00
COE Expiry Date:	28 Jun 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$61,000.00
COE Rebate Amount:	\$19,452.00
Total Rebate Amount:	\$25,602.00

The information contained herein is correct as at 20 Apr 2022

ОК

MV 44,000fr PV 25,602/2 NV 18,398/2

Talin lin 2014/2022



Posted: 05-Apr-2022



Honda Vezel 1.5A X

\$50,800

\$13,210 /vr 21-Oct-2015

1.496 cc

102,688 km

SUV

PREMIUM AD

\$0 Driveaway Available. Immediate Approval, In House And Bank Loan Available, Trade In Welcome Call Our Friendly Representatives For More Information Or For A Viewing Of The Car.

AL Autocar Pte Ltd

Posted: 15-Apr-2022



Honda Vezel 1.5A X

\$49,000

\$13,060 /vr

23-Sep-2015

1,496 cc

120,000 km

Available

Headunit Will Be Replaced! 1 Owner! Original Honda Modulo Bodykit! No PHV Usage. 100% Guaranteed! New Tyres! 100% Loan Available, Very Reliable And Fuel Efficient! 1 Owner Car, Low Maintenance And Low Monthly Repayment! Trade In Welcome! Flexible Ban..

CONSIGNMENT

Posted: 22-Feb-2022



Honda Vezel 1.5A X

\$45,800

\$12,170 /vr

18-Sep-2015

1,496 cc

SUV

SUV

Available

Accident Free, Well Maintained, Superb Condition, Spacious Interior, Low Fuel Consumption, STA/VICOM Evaluation Welcome, Flexible Loan Available! Bank And In House Loan Available! No Gimmicks! Trade In Welcome! Best Value For Money Drive! Don't Miss It, Contact.

This car comes with 6-mth sgCarMart Warranty - the best protection for your car. Learn More

Posted: 31-Mar-2022



Spruce up your car for 2022

We will soon be approaching a new year. Want to change a lucky colour for your car to enhance your luck in the year 2022? Find your preferred spray paint workshop to customise your unique colour,

Find out more!







Honda Vezel 1.5A S

\$46,800

\$13,250 /yr

22-Jun-2015

1,496 cc

77,000 km

SUV Available

Definitely Your Choice Of SUV For Short Term! Wear & Tear Replaced Accordingly. Well Taken Care By Previous Owner. Previous Owner Upgraded To MPV With Us. Attractive Interest From 1.88%! Warranty & Servicing Can Be Arranged For Peace Of Mind! New Coated Paint.

PREMIUM AD

SG Car Choice Pte Ltd

Posted: 09-Apr-2022



Honda Vezel 1.5A X

\$42,800

\$12,750 /vr Rare Gem, Elegant Mica Silver Vezel 1.5A With Nice Red Leather Seats. Genuine Low Mileage Done 97581km! Totally Good As New, Test

18-Jun-2015

1,496 cc

97,581 km

SUV

Available

PREMIUM AD

Drive/See To Certify. Fussy Car Lover Owner. Nice Car Number. New Paintwork. Road Tax Till Jun 22, 100% Accident Free. In House High Lake View Credit Pte Ltd

Posted: 17-Apr-2022

Honda Vezel 1.5A X

\$42,000

\$13,200 /yr

17-Apr-2015

1,496 cc

67,000 km

SUV

Available

Reliable And Best Compact SUV For Cat A Category! Spacious Interior And Huge Boot Compartment! Good Driving Agility! Welcome STA Evaluation For A Piece Of Mind! Flexible Financing Schemes And In House 100% Loan Available. Low Interest Rate. High Trade In. Conta...

PREMIUM AD

Monster Motors Pte Ltd

Posted: 22-Feb-2022

Honda Vezel 1.5A X

\$41,000

\$12,880 /yr

06-Mar-2015

1,496 cc

75,000 km

SUV

Available

Owner 2nd Car. Genuine Low Mileage. Non PHV Unit. Low Fuel Consumption. Reliable. Immaculate Condition And Very Well Maintained. Test Drive To Believe It! Best Compact SUV For Cat A Category!. Easy Maintenance. Popular Japanese SUV, With Spacious Interior And H...

DIRECT OWNER

Posted: 09-Apr-2022

Compare

1.5A X Honda

\$42,800

25-Feb-2015

Available

\$13,430 /yr

1,496 cc

103,200 km

SUV

SY0A21BA0009 / YEW TEE AUTOMOBILE TECH PTE LTD [417800] ENTRY DATE & TIME: 10/11/2021 17:55 (SGT) SUBMITTED BY: TOH LEI MING VERSION: 1 (10/11/2021 17:55 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

Please report <u>correctly</u> the details of the accident to speed up the claims process.

This Form must be completed by the Policyholder and/or the Authorised Driver

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 10/11/2021 17:55 (SGT) Date of Accident 05/11/2021 20:20 (SGT) Exact Location of Accident PIE, Singapore PIE TUAS BEFORE STEVENS ROAD EXIT Additional Location Information Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKU230L

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner LOO SHIAN CHYN NRIC No SXXXX540D **Email Address** SCOTCHHERE123@GMAIL.COM Mobile Phone No (Phone) +65-97608627 Alternative Phone No (Home) +65-97608627

VEHICLE PARTICULARS

Manufacturer Honda Model Vezel Variant Exact purpose for which vehicle was being used at time of Private use Are you claiming under your own insurance policy for repair to No - Claiming third party vour vehicle?

Vehicle Category Private car Transmission

Auto 0

INSURANCE COMPANY

Name of Insurance Company Liberty Insurance Pte Ltd Type of Coverage Comprehensive Fleet Policy Policy Number SI21V12439/VPE/R00 Cover Note Number

DRIVER

CC

Name of Driver LOO SHIAN CHYN NRIC No SXXXX540D

Date Of Birth 09/08/1964 Occupation Indoor Date Of Driving Pass 30/05/1992 Driving experience 29 YEARS AND 6 MONTHS Gender Mobile Number (Phone) +65-97608627 Alt, Phone Number (Home) +65-97608627 Email Address SCOTCHHERE123@GMAIL.COM APT BLK 836 JURONG WEST ST 81 #06-65 Address Address complement Postcode 640836 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Chain Collision Weather Conditions Raining Road Surface Wet OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? Yes Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No PASSENGER 1 **TEO KOK LEOW** Name Gender Male DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? No Was there any audio recorded? No DETAILS OF OTHER VEHICLE PROPERTY 1 Vehicle Registration Number SMA6737J Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car

Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	_
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SLD7366K
Vehicle Manufacturer	_
Vehicle Model	_
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	_
Insurance Company Name	-
Nature Of Damage	_
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

INJURED PERSONS DETAILS

INJURED 1

Name of injured person	TEO KOK LEOW
Gender	-
Phone No	-
Address	-
Address Complement	_
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKU230L
Were seat belts worn?	. 00
Was this injured conveyed to hospital by ambulance?	No
INJURED 2	
Name of injured person	LOO SHIAN CHYN
Gender	-
Phone No	-
Address	-
Address Complement	-
Post Code	-
Approximate Age Years Old	-
Injuries Sustained	-
Injured person in which vehicle?	SKU230L
Were seat belts worn?	Yes
Was this injured conveyed to hospital by ambulance?	No

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &

Oriver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

B: SKU230L B: SKD7366K

8 7× A * C 2 ->

PIE (TUNS)

5 Nov 2021, aro	me 8 20pm	7 1	Inepope d	
				e. 1 (P
met an accident i	+ (PIE) Per	fore Steum	64.	
e car (SLD 7366K)	in front od	me sudden	e-bate i	hadauit a
mings to stop in	time, How	the the	hide bet (sh	146737
thind dib not and b	any onto my	Vehide (St	(1030F).	
on bation best f	ndly Dix	to the impor	+ 1 my	
chicle bring only the	Aront Vehi	ct.		100
ou can refer to 1	ne accident	photos for	word informat	10.0 -
ONE OF THE PROPERTY OF THE PRO	Jaanon üst			1000
				109
				bIO Pice
	3003026			distribution
	- OVI	Chin	Sluckos agli Intiquad	of bayesyou
	mange to stop in third die not and be ear partien pretty be thicke bring only the	thind did not and bong onto my ear portion prety body. Dix which bong onto the Aront Webs	mange to stop in time, However the Va third did not and bong onto my Vehicle (Sk ear parties pretty body. Dix to the import Schiele bring onto the Smoot Vehicle.	the car (SLD 7366E) in the thought of me sudden e-bake is munged to stop in time (However the Nathicle 124 (Structure) the Nathicle 124 (Structure) did not and bary onto my Vehicle (SKU2301): ear portion pretty body. Dix to the impact i my fehicle bang onto the Aront Vehicle. Ou can refer to the accident photos for more information.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date &

Time

Driver's Signature (If driver is not the policyholder) / Date

mary

Witnessed by Reporting Centre Personnel AUTO PTE LTD

① KAKI BUKIT #01-49 SINGAORE 415875

4457

-65 64524584

≥g No: 201929175W

Vehicle number: Make and model:

Chassis:

SKU230L Honda Vezel RU1-1021656

2015 List price Qty Spare parts 800.00 953.30 PD V \$ Tailgate 1 56.50 NEG \$ 1 Tailgate "Vezel" emblem \$ 52.00 1 Tailgate windscreen glasss upper rubber moulding √ 52.00 \$ Tailgate windscreen glass lower rubber moulding 1 \$ $\sqrt{52.00}$ Tailgate windscreen glasss RH rubber moulding 1 \$ 1/52.00 Tailgate windscreen glass LH rubber moulding 413.30 BRV \$ Tailgate LH lamp 335.00 √ 38.50 NECL \$ Tailgate LH lamp gasket 1 413.30 BRV \$ 335.00 Tailgate RH lamp \$ 138.50 NEG Tailgate RH lamp gasket 231.00 BK \$ Tailgate outer garnish \$ 28.00 NEG Tailgate outer garnish emblem \$ 55.10 Tailgate RH number plate lamp \$ 55.10 1 Tailgate LH number plate lamp \$ 1,020.70 NDX Tailgate reverse camera 1 \$ / 154.70 BRV 1 Tailgate inner trim board \$ 189.00 JAN Tailgate lock 1 \$ 27.50 NDX 1 Tailgate lock catch \$ 28.60 ND Tailgate inner pull handle \$ 182.00 1 Tailgate RH damper \$ 182.00 Tailgate LH damper 1 \$ 96.80 TNV Tailgate weatherstrip \$ 465.70 BR Rear bumper 1 \$ 250.00 BRV 1 Rear bumper lower cover 129.00 00-141.10 BR: \$ 1 Rear bumper LH reflector \$ / 198.00 BR 1 Rear bumper LH side cover \$ V 26.50 1 Rear bumper LH side retainer V 26.50 \$ 1 Rear bumper RH side retainer \$ 487.60 BRV 1 LH taillamp \$ 44.20 NECL 1 LH taillamp gasket \$ -487.60 BRV 1 RH taillamp \$ 20.00 44.20 NECL 1 RH taillamp gasket \$ 415.60 DDV 1 End panel \$ 109.00 BRV End panel inner garnish 1 \$ 65.10 1 End panel antenna sensor \$ 85.60 1 End panel buzzer sensor 485.90 BR \$ 1 Rear compartment panel tray garnish 430.30 NDX Rear compartment panel tray garnish top cover board

V

1	Rear LH fender	\$	✓ 884.80 DD ✓
1	Rear LH fender arch moulding	\$	V 198.00 BRV
1	Rear LH fender splash shield	\$	145.90 NDX
1	Rear LH fender inner trim board	. \$	/ 298.50 BRV
1	Rear LH fender air vent	\$	45.30 NDV
	Rear RH fender	\$	884.80) D.P.
1		\$	/ 198.00
1	Rear RH fender arch moulding	\$	145.90 NDX
1	Rear RH fender splash shield		
1	Rear LH fender inner trim board	\$	√298.50 BR
1	Rear RH fender air vent	\$	✓ 45.30 BR ✓
1	Bonnet	\$	892.30 NDX
1	Bonnet RH hinge	\$	48.50 2 NDX
1	Bonnet LH hinge	\$	48.50
1	Bonnet lock	\$	98.00 NDZ
1	Bonnet RH inner side rubber moulding	\$	37.50
1	Bonnet LH inner side rubber moulding	\$	37.50
1	Bonnet RH inner centre rubber moulding	\$	23.00 LNDX
1	Bonnet LH inner centre rubber moulding	\$	23.00
1	Bonnet insulator	\$	122.30
1	Front bumper	\$	762.70 801.70 BRV
1	Front bumper RH side retainer		22.80 NEC
1	Front bumper LH side retainer	\$	√ 22.80) 227.70 BP.
1	Front bumper RH fog lamp	\$	308.90 327.70 BR
1	Front bumper RH fog lamp bracket	\$	27.00 NSX
1	Front bumper RH fog lamp garnish	\$	30890 327.70 BRV
1	Front bumper LH fog lamp	\$	
1	Front bumper LH fog lamp bracket	\$	27.00 NDX
1	Front bumper LH fog lamp garnish	\$	46.00 BR
1	Front bumper lower centre grille	\$	78.40 BR
1	Front bumper lower spoiler	\$	279.00 381.00 BA
1	Front bumper reinforcement	\$ \$ \$ \$	274,70 321.00 PM
1	Front bumper reinforcement RH top moulding	\$	38.00 \ NDX
1	Front bumper reinforceemnt LH top moulding	\$	17.10 NDX
1	Front bumper towing cover	\$	
1	Front grile		250.00 351.80 BR / 23.40 NEC
1	Front grille emblem	\$	-0 00 RP.
1	Front grille centre bracket Front grille chrome moulding	\$	10000 PO /
2	Front grille outer cover	\$	421 00 BRV
1	RH headlamp assy	\$	194. to 1795 50 BEV
1	RH headlamp lower bracket	\$	17 19,10
1	RH headlamp side bracket	\$	38.90 42.00 BR-
1	LH headlamp assy	\$	1715, 101,795.50 BRV
1	LH headlamp lower bracket	\$	12.00
1	LH headlamp side bracket	\$	38.90 42.00 BR
1	Front horn (low tone)	\$	110.50 } 61NX
1	Front horn (high tone)	\$	110.50
1	Front outside temperature sensor	\$	83.00
1	Front outside temperature sensor bracket	\$	27.00
1	Front RH fender arch moulding	\$	180.00 220.00 7 BBV
1	Front LH fender arch moulding	\$	180.00 220.00
1	Support panel	\$	586 20 DA
			528.00

1	Radiator	\$		1,376.60
1	Radiator RH side guide	\$		31.80
1	Radiator LH side guide	\$		-31.80 \ ND
1	Aircon condenser	\$		568.30
1	Air duct	9	,	127.80
				22 441 40
		\$		23,441.40
		-20% \$		4,688.28
		9)	18,753.12
Qty	Spare parts		Special ne	tt price
1set	Bonnet insulator clips	S		100.00 NNX
1set	Front bumper clips	9		100.00 NEW
1set	Front RH fender splash shield clips	9		80.00 NNX
1set	Front RH fender arch moulding clips	S		80.00 NNX
1set	Front LH fender splash shield clips	9		80.00 NNX
1set	Front LH fender arch moulding clips	9		80.00 W NT
1set	Front grille clips	S		70.00 NEW
1	Radiator coolant	S		YUN 00.00
1	Front number plate	9		70.00 BR
1	Tailgate windscreen glass sealant	9		80.00 } NECV
1	Tailgate windscreen glass inner seal	. 5		-50.00
1set	Tailgate inner trim board clips	9		80.00 NEW
1set	Tailgate outer garnsih clips	5		70.00 NEC
1set	Rear bumper clips	5		-100.00 NECV
1set	Rear bumper reverse sensors	9		320.00 Se
1set	Rear fender RH arch moulding clips	5		-80.00 } NEW
1set	Rear fender LH arch moulding clips	5		80.00
1	Rear fender RH sealant	9		80.00 NEW
1set	Rear fender RH inner trim board clips	5		-80.00 LNECV
1set	Rear fender LH inner trim board clips	5		-80.00
1	Rear fender LH sealant	9		80.00] NNX
1	Rear number plate			70.00
1	End panel	9		70.00 NNX
lset	End panel inner garnish clips		30.00	50.00 N€C
177	NT PORTION)	,	1 2 00	1 000 005
	r charges to remove, check, replace and reinstall damages bodyparts.		400.00	1,000.00
To par	nel beating, cut / weld and re-align all affected panels			
Spray	painting on affected panels		\$ 400.00	-900.00
Check	wiring and lighting system		8	70.00 NNX
				40.00-1111
2.2	rust coating chemical on affected panels		5	40:00-MM X
Remo	ve and replace aircon condenser, pipes and hoses to assist repair. To refill aircon g	as S	5	40.00-NNX 40.00-NNX 250.00-2 NNX
Remo	ve and replace radiator assy, pipes and fan assy to assist repair. To refill coolant	- 6	\$	250.00

Refocus and adjust headlamps assy
(RERR PORTION) Labour charges to remove, check, replace and reinstall damages bodyparts. To panel beating, cut / weld and re-align all affected panels
Spray painting on affected panels
Check wiring and lighting system
Apply rust coating chemical on affected panels
Remove and replace tailgate windscreen glass to assist repair
Remove and replace tailgate inner components to assist repair
Remove and replace tailgate reverse camera to assist repair
Remove and replace rear bumper reverse sensors to assist repair
Remove and replace rear inner trims, garnish and boards to assist repair
Remove and reinstall petrol tank, pipes and hoses to sensors to assist repair
Remove and reinstall roof lining, seats and carpet to assist repair
Roseway N. W.

\$	1000,00	1,600.00
\$	1000,00	1,400.00
\$		100.00 NNX
\$		80.00 NN
\$	120,00	250.00
\$	80.00	180.00
\$		100.00- NN
\$	60:00	100.00
\$	80.00	220.00
\$		150.00 NNX
\$		380.00 NN

28,003.12

-60.00 NN

Survey Resurvey

8/11/2021

Totim Im

1430hrs

1630 hrs

Lump sum repair Repair days 10 Pauts 13484.80 SN 1190.00 Labour 3140.00 17814.80 @ 2070 3562.96 14,251.84

Total: \$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

LS 14,250/2

75/m hun 29/4/2022

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAORE 415875

Tel: +65 64524457 Fax: +65 64524584

Company Reg No: 201929175W

Supplementary

Vehicle No: Model and make:

SKU230L Honda Vezel

Parts			List	price 2015	
RH rear door inner trim board		\$	355.	OU 650.40 BA	21
RH rear door lock		\$	196.30	196.30 JA	1/
LH rear door inner trim board		\$	355.0	-650.30 BA	RV
LH rear door lock		\$	196.30	196.30 J	1V
Rear bumper lower cover		\$	RPTX	251.00 BA	2 /
Rear compartment tool sponge tray		\$	14	✓ 226.40 B	R
Exhaust silencer		\$	517.7	700.20 D	DV
Exhaust silencer gasket		\$	40.50	140.50 NE	CV
		\$		2,911.40	
	-20%	\$		582.28	
		\$		2,329.12	
Parts			Special n	ett price	
RH rear door inner trim board clips		\$	30.00	60.00 7	E11 /
		\$	30 (6)	60.00	CUV
Rear bumper chrome step moulding		\$	250.00	380.00 DD	
End panel chrome moulding		\$		√250.00 DD	V
Labour					
Remove and replace exhaust silencer and gasket to assist repair		\$		120.00 N	X
Rosurvey					1
	RH rear door inner trim board RH rear door lock LH rear door lock Rear bumper lower cover Rear compartment tool sponge tray Exhaust silencer Exhaust silencer gasket Parts RH rear door inner trim board clips LH rear door inner trim board clips Rear bumper chrome step moulding End panel chrome moulding Labour Remove and replace exhaust silencer and gasket to assist repair	RH rear door inner trim board RH rear door lock LH rear door inner trim board LH rear door lock Rear bumper lower cover Rear compartment tool sponge tray Exhaust silencer Exhaust silencer gasket Parts RH rear door inner trim board clips LH rear door inner trim board clips LH rear door inner trim board clips Rear bumper chrome step moulding End panel chrome moulding Labour Remove and replace exhaust silencer and gasket to assist repair	RH rear door inner trim board RH rear door lock LH rear door inner trim board LH rear door lock Rear bumper lower cover Rear compartment tool sponge tray Exhaust silencer Exhaust silencer gasket S Parts RH rear door inner trim board clips LH rear door inner trim board clips LH rear door inner trim board clips S Rear bumper chrome step moulding End panel chrome moulding S Labour Remove and replace exhaust silencer and gasket to assist repair \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	RH rear door inner trim board RH rear door lock LH rear door inner trim board LH rear door lock Rear bumper lower cover Rear compartment tool sponge tray Exhaust silencer Exhaust silencer gasket Special n RH rear door inner trim board clips LH rear door inner trim board clips LH rear door inner trim board clips Rear bumper chrome step moulding End panel chrome moulding Labour Remove and replace exhaust silencer and gasket to assist repair	RH rear door inner trim board RH rear door lock LH rear door lock LH rear door lock S 196-30

9/11/2022 Talin Im 1630hrs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
 Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Final amount: \$

3,199.12