

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0379/21

DATE : 05-NOV-2021

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

S(079909)

TEL : 63696111

FAX : 62247175

OWNER'S NAME : PRAVEEN ARUJA

ADDRESS : 28 UPPER SERANGOON VIEW

#06-35

S(534207)

TELEPHONE NO : 98214692

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : *

VEHICLE NO : SFK7999T

MODEL CODE : FRLARBZJ11UEA--A--

MODEL/YEAR : NISSAN QASHQAI 1.2

ENGINE NO : HRA2219179A

CHASSIS NO : SUNFEAJ11U1549286

MILEAGE : 39130 KM

DATE IN : 05/11/2021

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : HAMZAH

ACCIDENT DATE : 03/11/2021

- 96450079

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFK7999T

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO REPAIR REAR PANEL AND RENEW REAR BUMPER.	700.00	
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	600.00	
3	ZZ/003	REMOVE AND INSTALL REAR BUMPER SENSOR TO RENEW AND RESET.	110.00	
4	ZZ/004	SUPPLY REAR LICENCE PLATE.		
		TOTAL LABOUR CHARGES	1410.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFK7999T

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	REMARKS
1	SUNDRIES	NPN			50.00	
2	REAR LICENCE PLATE	RLP			60.00	
3	REAR BUMPER TOW HOOK COVER	85071-4EA0A	18.80			
4	SENSOR-REVERSE	SENSOR			250.00	
5	REAR BUMPER STAY LH	H5211-4EAMA	141.00			
6	REAR BUMPER STAY RH	H5210-4EAMA	141.00			
7	REAR BUMPER REINFORCEMENT	H5030-4EAMA	691.50			
8	REAR BUMPER SIDE BRKT LH	85221-4EA0A	38.90			
9	REAR BUMPER SIDE BRKT RH	85220-4EA0A	38.90			
10	ENERGY ABSORBER REAR BUMPER	85090-4EA0B	155.60			
11	REAR BUMPER RETAINER	79184-4EA0A	25.70			
12	CLIP REAR BUMPER @ \$8.00 EACH	85284-JD00A	80.00			
13	REAR BUMPER FASCIA	85022-4EA0H	876.40			
SUB TOTAL			2207.80	0.00	360.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			441.56	0.00	0.00	
GRAND TOTAL			1766.24	0.00	360.00	
OVERALL TOTAL			2126.24			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFK7999T

TOTAL LABOUR CHARGES	1410.00
TOTAL SPARE PARTS CHARGES	2126.24

GRAND TOTAL	3536.24 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.