

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC21011346/T1vf3e2	
	300 BEACH ROAD SINGAPORE 1995	#17-04/07 THE CONCOURSE 55		Date:	22/11/2021	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	YP 6405X	Veh. Inspected		GBK 5850Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	21/21/21/VC00/025124	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		08/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA DYNA 150	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2020	
	Chassis No.	JTFAT35YX0K215330	Colour		SILVER	
	Odometer	56928 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	155 R12 (D)	BRIDGESTONE		6/6 mm	
	L/H Rear Tyre	155 R12 (D)	BRIDGESTONE		6/6 mm	
4.	Description of Damages					
	THE VEHICLE SU	STAINED DAMAGES AT THE O/S REAR PORTION.				
5.	General Information					
	Accident Date	05/11/2021	Inspect Date /	Time	15/11/2021 ( 03:00 PM )	
	Survey held at	JL AUTO SERVICES PTE LTD				
		BLK 3006 UBI ROAD 1 #01-346 KAMPONG UBI INDUSTRIAL ESTATE SINGAPORE 408700				
5a. Remarks						
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC21011346/T1vf3e2

Inspected By

MOHAMAD TAUFIKH

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A
Automotive Assessor

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$ 

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.