



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

Our Services : *Automotive Surveying* | *Vehicle Valuation*
Motor Claims Investigation | *Evaluation & Consultation*

Reference : TY5/TA/10046/9992/TP/09.21

Date : 18 October 2021

Vehicle no : SJV 9992T ✓

To: David Gao Hui
c/o 2 Kaki Bukit Ave 2
#01-36, Kaki Bukit Autohub
Singapore 417921

VEHICLE INSPECTION REPORT

Name of Workshop : Sheng Li Lai
Place of inspection : 2 Kaki Bukit Ave 2 #01-36, Kaki Bukit Autohub, Singapore 417921
Date of Accident : 11 September 2021
Date of Inspection : 11 October 2021

VEHICLE PARTICULAR

Registration No.	: SJV 9992T	Chassis Frame No.	: WBA8E32070K497570
Make / Model	: BMW 318i Sedan LED NAV	Engine No.	: G1911194B38B15A
Year of Registration	: 2015	Odometer Reading	: 84,687 KM
Class / Type	: Saloon	Colour	: White

VEHICLE CONDITION

General Condition	: Very Good	Steering	: Serviceable
Paintwork	: Very Good	Foot/ Parking Brake	: Serviceable

TYRE CONDITION

	<u>Size</u>	<u>Thread Balance</u>
Front L/H :	PIRELLI 225 / 50 R17	8mm
Front R/H :	PIRELLI 225 / 50 R17	8mm
Rear L/H :	PIRELLI 225 / 50 R17	8mm
Rear R/H :	PIRELLI 225 / 50 R17	8mm

* The above is an estimate of the remaining life of the tyre thread in percentages

COST OF REPAIR

	<u>Repairer S\$</u>	<u>Adjuster S\$</u>
Parts	\$ 2,439.60	\$ 2,317.62
Labour	\$ 1,940.00	\$ 1,500.00
	<u>\$ 4,379.60</u>	<u>\$ 3,817.62</u>

TY5 Recommendation

Lump Sum Repair : 2250
\$ 3,050.00 ✓

Estimated Repair Duration :

4 3 ✓

working days (excluding Sat, Sun & Public Holidays)

NOTE : The information contained in these documents may be privileged and confidential, and is intended for the exclusive use of the addressee designation. If you are not the addressee, any enclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited.



TY5 CONSULTANCY

(Registration No.: 58429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5845 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10046/9992/TP/09.21
Date : 18 October 2021
Vehicle no : SJV 9992T

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
<u>LIST ITEMS:-</u>					
1	1 pc	rear bumper	deformed	\$ 1,194.70	\$ 1,194.70 ✓
2	1 pc	rear bumper reinforcement	buckled	\$ 592.60	\$ 592.60 ✓ 485
3	1 pc	rear bumper l/h side retainer	broken	\$ 127.30	\$ 127.30 ✓ cut
4	1 set	rear bumper clips	necessary	\$ 35.00	\$ 35.00 ✓
5	1 pc	reverse sensor @S\$245.00	not working	\$ 490.00	\$ 490.00 ✓ 200-245
6	1 pc	rear end panel	dented		
				repair	repair
				\$ 2,439.60	\$ 2,439.60
		Less	5%		\$ 121.98
				\$ 2,439.60	\$ 2,317.62

Total \$ 2,439.60 \$ 2,317.62



TY5 CONSULTANCY

(Registration No.: 53429875C)

Address : 50 Chin Swee Road #09-04, Thong Chai Building, Singapore 169874

Contact : +65 8788 5345 | Email Address : admin@ty5group.com.sg

*Our Services : Automotive Surveying | Vehicle Valuation
Motor Claims Investigation | Evaluation & Consultation*

Reference : TY5/TA/10046/9992/TP/09.21
Date : 18 October 2021
Vehicle no : SJV 9992T

ASSESSMENT SCHEDULE

<u>SN</u>	<u>Qty</u>	<u>Descriptions</u>	<u>Conditions</u>	<u>Repairer's Estimate</u>	<u>Surveyor's Revised</u>
		B/F		\$ 2,439.60	\$ 2,317.62
7		To panel beat and renewal of all necessary damaged body parts		\$ 1,000.00	\$ 800.00 400
8		To remove and reinstall reverse sensor		\$ 140.00	\$ 100.00 30
9		To putty and spray-paint of affected areas		\$ 800.00	\$ 600.00 400
				<u>\$ 1,940.00</u>	<u>\$ 1,500.00</u>

Total \$ 4,379.60 \$ 3,817.62