

LK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

國際汽車維修 KT MOTORWERK

Blk 3012 Bedok Ind. Park E #01-2020 Singapore 489978.
Bedok North Ave. 4) Tel: 98287487 Fax: 6448 5177
Email: ktmotorwerk@hotmail.com
Reg. No.: 53373462B

Acknowledged by Repairer

Signature: **Vehicle Model :** BMW 218i

Date: **Accident Date :** 06.11.2021

Original Reg Date : 19.03.2021

SMY6754H

Chassis : WBA12AK0507H60093

TP Ins. : AIG

Cecilia.

ESTIMATE

Sn	Qty	Description	List	Final price
1	1	Front bumper <i>to be</i>	1,245.80	1245.8
2	1	Front bumper lower grille	228.70	228.7
3	1	Front bumper bracket LH	235.80	235.8
4	1	Front bumper reinforcement	425.80	425.8
5	1	Front bumper sponge	285.90	285.9
6	1	Front bumper foglamp	570.80	570.8
7	1	Front bumper foglamp cover	198.50	198.5
8	1	Front bumper sensor	265.20	265.2
9	1	Front bumper sensor holder	45.60	45.6
10	1	Front bumper lower support beam	345.60	345.6
11	1	Front bumper grille	228.70	228.7
12	1	Front fender	728.30	728.3
13	1	Front fender inner cowling	198.60	198.6
14	1	Front headlamp	2,528.30	2528.3
15	1	Front headlamp lower bracket	198.70	198.7
16	1	Front Rim	987.60	987.6
17	1	Front Bonnet	1,987.60	1987.6
18	1	Front Bonnet lock	387.90	387.9

3774.10

subtotal 11,093.40
PART DISC 10% 9,984.06

3396.69

QTY SPECIAL NETT ITEMS

1	1 set	Front bumper Clips		30.00
2	1 set	Front fender inner cowling clips		600.00

30

Labour charge

Panel Beating	1,800.00
Spray painting - Pearl	1,800.00
Check Wiring on headlamp and focussing	180.00
Anti rust	100.00
Remove and install front sensor	120.00
To perform computerize wheel alignment.	120.00

3.5K

Total \$ 14,734.06

Total 4406.69

L/S: 3.5K

Adrianly

08/11/21

03 Days