



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0922/2021/TF
DATE : 10-Nov-21
WIP : 53068

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY
YOUR INSURED VEH NO : EZ 28 A

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR KARTIK KRISHNAMURTHY
ADDRESS : 16 EWE BOON ROAD
#03-03
SINGAPORE 259324
TELEPHONE : HP +65 9643 4040
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2070177552
VEHICLE NO : **SKL 9086 A**
MODEL CODE : AUDI A4 2.0 TFSI S tronic
MODEL YEAR : 23/12/2020
ENGINE NO : DEM 027329
CHASSIS NO : WAUZZZF45MN004658
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Dec-20
PLACE OF ACCIDENT : ALONG OPHIR ROAD



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKL 9086 A

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$	360.00	✓
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,400.00	750
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$	2,000.00	1100
4	TO RENEW RHS REAR RIM AND CARRY OUT WHEEL ALIGNMENT.	S/N \$	280.00	✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,232.00	



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKL 9086 A

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Repair</i>	1	\$ 2,342.00	+
2	REAR BUMPER FIXING PARTS <i>new</i>	1	\$ 166.00	+
3	REAR BUMPER SECURING STRIP - UPPER / LOWER <i>new</i>	2	\$ 335.00	+
4	REAR BUMPER SPOILER <i>new</i>	1	\$ 249.00	+
5	REAR BUMPER TOP GUIDE SECTION - LH / RH <i>?</i>	2	\$ 46.00	+
6	REAR BUMPER GUIDE SECTION - RH <i>HP</i>	1	\$ 45.00	+
7	REAR WHEEL HOUSING LINER - RH <i>m</i>	1	\$ 240.00	+
8	REAR WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>	1	\$ 139.00	+
9	REAR TYRE RIM - RH <i>new</i>	1	\$ 1,155.00	+
10	SUNDRIES <i>?</i>		\$ 250.00	?
TOTAL SPARE PARTS		:	\$ 4,967.00	
TOTAL LABOUR CHARGES		:	\$ 4,232.00	
GRAND TOTAL		:	\$ 9,199.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lij*
SURVEYED DATE : *16/11/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *not authorized, 04 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT