

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21011358/AVF3N2**Date:** 04/03/2022**REFERENCE**

Insured/Claimant: - Policy No: D19MPC0006136_01
Date of Loss: 05/11/2021 Nature of Claim: OD Claim No: MPC2021D0004820

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKW8648C**
Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6E (A) Engine No: P520330011
Reg. Date: 18/11/2015 (Man. Year: 2015) Chassis No: JM6BM42A8G0324331
Colour: Blue Odometer: 32830 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$46,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,852.56	4,403.76	2,448.80	35.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,470.00	1,830.00	55.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,152.56	5,873.76	4,278.80	42.15
Approved Total (Overridden) (S\$)		4,700.00		
- Excess (S\$)	600.00	600.00	0.00	0.00
Nett Amount (S\$)	9,552.56	4,100.00	5,452.56	57.08

INSPECTION

Date of Assignment: 08/11/2021
Date Inspected: 09/11/2021 Inspected At: Hua Meng Spray Painting Workshop (HQ)
No 1 Kaki Bukit Avenue 6, #01-61 Autobay@Kaki
Bukit
Singapore 417883
Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Mar 2022)

Parts: 143 MAZDA 3 1.4 SEDAN 1.5L SP.6E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SKW8648C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,165.70 FL	*971.00 FL
2	1		*FRONT BUMPER SIDE HOLDER	N/s Damaged	49.80 FL	*24.90 FL
3	1		*FRONT BUMPER LH FOD LAMP	Cracked	442.80 FL	*351.00 FL
4	1		*FRONT BUMPER LH SIDE GARNISH	Cut	85.00 FL	*85.00 FL
5	1		*FRONT BUMPER REINFORCEMENT	Dented	712.10 FL	*467.00 FL
6	1		*FRONT GRILLE	Cracked	150.80 FL	*150.80 FL
7	1		*FRONT GRILLE EMBLEM	Necessary	55.80 FL	*55.80 FL
8	1		*FRONT GRILLE RIM	N/s Cracked	445.60 FL	*222.80 FL
9	1		*FRONT LH HEADLAMP	Cracked	974.40 FL	*974.40 FL
10	2		*FRONT LH HEADLAMP BULBS	Not Necessary	120.00 FL	*- FL
11	1		*FRONT LH FENDER	Distorted	420.80 FL	*420.80 FL
12	1		*FRONT LH FENDER INNER SHIELD	Torn	122.30 FL	*122.30 FL
13	1		*FRONT SUPPORT PANEL	Cracked	591.90 FL	*591.90 FL
14	1		*FRONT SUPPORT PANEL TOP COVER	Not Necessary	116.90 FL	*- FL
15	1		*FRONT LH WHEEL BEARING	Damaged	682.60 FL	*367.00 FL
16	1		*FRONT LH KNUCKLE ARM	Not Necessary	483.20 FL	*- FL
17	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
18	1		*SET FRONT LH FENDER INNER SHIELD CLIPS	Necessary	60.00 FS	*30.00 FS
19	1		*FRONT LH SPORT RIM	Cut	1,156.80 FS	*500.00 FS
20	1		*FRONT LH TYRE	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,176.50	5,364.70
- List Item Discount on L Items 20.00/20.00% (S\$)	1,323.94	960.94
Total Parts (S\$)	6,852.56	4,403.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WHEEL ALIGNMENT	New	100.00	80.00
2	REMOVE & REFIX AIRCOND FILL IN GAS	New	150.00	80.00
3	REMOVE & REFIX FRONT LH SUSPENSION	New	250.00	60.00
4	REMOVE,REPLACE & REPAIR CONSISTENT TO THE ACCIDENT	New	1,200.00	500.00
5	RESPRAY PAINTING	New	1,100.00	400.00
6	TO DIAGNOS, TROUBLESHOOT AND TO REPAIR START STOP MOTOR	New	500.00	350.00
			Gross Labour Cost (\$)	3,300.00
				1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >