

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : CHNG SOO SOO AMY

Make/Model : MAZDA 3

Vehicle No : SKW8648C

Accident date : 05.11.2021

No	DESCRIPTION	Qty	Amount (\$)
List Items			
1	Front bumper	1	\$ 1,165.70
2	Front bumper side holder @ \$24.90	2	\$ 49.80
3	Front bumper LH fod lamp	1	\$ 442.80
4	Front bumper LH side garnish	1	\$ 85.00
5	Front bumper reinforcement	1	\$ 712.10
6	Front grille	1	\$ 150.80
7	Front grille emblem	1	\$ 55.80
8	Front grille rim @ \$222.80	2	\$ 445.60
9	Front LH headlamp	1	\$ 974.40
10	Front LH headlamp bulbs @ \$60.00	2	\$ 120.00
11	Front LH fender	1	\$ 420.80
12	Front LH fender inner shield	1	\$ 122.30
13	Front support panel	1	\$ 591.90
14	Front support panel top cover	1	\$ 116.90
15	Front LH wheel bearing	1	\$ 682.60
16	Front LH knuckle arm	1	\$ 483.20
			<hr/>
			\$ 6,619.70
		Less 20% Disc	\$ 1,323.94
		Total	<hr/>
			\$ 5,295.76
 Special Nett Items			
1	Front bumper clips (1 set)	1	\$ 60.00
2	Front LH fender inner shield clips (1 set)	1	\$ 60.00
3	Front LH sport rim	1	\$ 1,156.80
4	Front LH tyre	1	\$ 280.00
		Total	<hr/>
			\$ 1,556.80
 Labour Cost			
1	To check wheel alignment		\$ 100.00
2	Remove & refix aircond fill in gas		\$ 150.00
3	Remove & refix front LH suspension		\$ 250.00
4	Remove ,replace & repair consistent to the accident		\$ 1,200.00
5	Respray painting		\$ 1,100.00
		Total	<hr/>
			\$ 2,800.00
		Grand Total	<hr/> <hr/>
			\$ 9,652.56