

HUA MENG SPRAY PAINTING WORKSHOP

1, Kaki Bukit Avenue 6, Blk C #01-61 / 01-34, Singapore 417883

Autobay @ Kaki Bukit

Tel: 6747 8064, 6746 5519 / 9666 9680 Fax: 6743 4896

ESTIMATE

Name : CHNG SOO SOO AMY

Make/Model : MAZDA 3

Vehicle No : SKW8648C

Accident date : 05.11.2021

No	DESCRIPTION	Qty	Amount (S\$)
List Items			
1	Front bumper <i>Distorted</i>	1	\$ 1,165.70 ✓
2	Front bumper side holder @ \$24.90 <i>Dayd LH</i>	2	\$ 49.80 <i>24.90</i>
3	Front bumper LH fod lamp ?	1	\$ 442.80 ?
4	Front bumper LH side garnish <i>cut</i>	1	\$ 85.00 ✓
5	Front bumper reinforcement ?	1	\$ 712.10 ?
6	Front grille ?	1	\$ 150.80 ?
7	Front grille emblem ?	1	\$ 55.80 ?
8	Front grille rim @ \$222.80 ?	2	\$ 445.60 ?
9	Front LH headlamp <i>Cracked</i>	1	\$ 974.40 ✓
10	Front LH headlamp bulbs @ \$60.00	2	\$ 120.00 ✓
11	Front LH fender <i>Distorted</i>	1	\$ 420.80 ✓
12	Front LH fender inner shield <i>tom</i>	1	\$ 122.30 ✓
13	Front support panel ?	1	\$ 591.90 ?
14	Front support panel top cover ?	1	\$ 116.90 ?
15	Front LH wheel bearing ?	1	\$ 682.60 ?
16	Front LH knuckle arm ?	1	\$ 483.20 ?
			\$ 6,619.70
Less 20% Disc			\$ 1,323.94
Total			\$ 5,295.76

Special Nett Items

1	Front bumper clips (1 set)	1	\$ 60.00 <i>-30</i>
2	Front LH fender inner shield clips (1 set) <i>Free</i>	1	\$ 60.00 <i>-30</i>
3	Front LH sport rim <i>cut</i>	1	\$ 1,156.80 <i>500</i>
4	Front LH tyre <i>new</i>	1	\$ 280.00 <i>+</i>
Total			\$ 1,556.80

Labour Cost

1	To check wheel alignment	\$ 100.00 <i>-80</i>
2	Remove & refix aircond fill in gas	\$ 150.00 ?
3	Remove & refix front LH suspension	\$ 250.00 ?
4	Remove ,replace & repair consistent to the accident	\$ 1,200.00 <i>-500</i>
5	Respray painting	\$ 1,100.00 <i>-400</i>
Total		\$ 2,800.00

Grand Total \$ 9,652.56

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Admin
L/s 09/11/21

05 Days
Not Authorised.
EXCESS: To be advised