

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305493554 Via Fax : Email
Date : 08-11-21 Your Insured : SMD 303B
Time of Fax : - Date of Acc : 07-11-21

Attn: Motor Claims Department

AlG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH C 7806K

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Ms. Loke Wei Yieng (yy)	Tel: 62148355 or HP: 86285336
◆ Jumani Bin Masudin	Tel: 6214 8315 or HP: 9635 5305
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

lokewy@sparkcarcare.com
Fax no. 65468156

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully



For Vice President
Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC7806K

Date: 08/11/2021

Make : HYUNDAI

Insurance: AIG

Model : IONIQ(G2)

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT BUMPER COVER			\$430.90
10	FRT BUMPER CLIPS			\$22.00
1	FRT BUMPER SIDE BRACKER RH			\$28.00
1	FRT BUMPER MOULDING CENTRE UPPER			\$368.50
1	HEADLAMP RH			\$1,993.65
1	DAY LIGHT RH			\$642.50
1	FRT BUMPER SIDE GRILLE RH			\$93.45
1	EMBLEM BLUE – DRIVE RH			\$26.60
	SUB TOTAL			\$3,605.60
	LESS 20%			\$721.12
	DISCOUNTED TOTAL			\$2,884.48
	FRT FENDER ADVERTISEMENT LOGO RH			\$100.00 nett
				\$100.00 nett
	Labour Charge			
	PANEL BEATING			\$1,050.00
	SPRAY PAINTING CHARGE			\$600.00
	CHECK ALL LIGHTING			\$60.00
	TOTAL LABOUR			\$1,710.00
	ESTIMATE TOTAL			\$4,694.48

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Date/Time: 08.11.2021 11:11

Page : 1

am: ARC Repair TP(CFSO)1

JOB CARD

Sales Order: 4137895

JC NO 305493554

OMER

IS CITYCAB PTE LTD

OMER NO. 7010070

IESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

(R) 65551188

(O)

(P)

DUNT CARD NO.

REGN NO.:

SHC7806K

MILEAGE

MAKE:

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN 08.11.2021 09:15

YR OF MANU.

06.08.2019

TARGET DATE

CHASSIS CODE

KMHC851CVKU165203

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 07.11.2021

ATURE: 3p 07.11.2021

NO

LABOR CODE

DESCRIPTION



KED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

edgement Slip

Exit Pass

lo.: SHC7806K

YY

Vehicle No.:

SHC7806K

Service Advisor

Signature/Date

Name of Service Advisor

Date

urned to Service Reception upon collection

To be kept by Security Guard