COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SHC7806K

Make

: HYUNDAI

Model

: IONIQ(G2)

Date: 08/11/2021

Insurance: AIG

MVA: MS. LOKE YY

Qty	Parts Description / Labour	Туре	Unit Price	Amount
	FRT BUMPER COVER	1355477	7 (49)	Le \$430.90
10	FRT BUMPER CLIPS	1	1	Me \$22.00
	FRT BUMPER SIDE BRACKER RH			NN \$ \$28.00
1	FRT BUMPER MOULDING CENTRE UPPER	1		at \$368.50
1	HEADLAMP RH		a	\$1,993.65
1	DAY LIGHT RH			↑↑ X \$642.50
1	FRT BUMPER SIDE GRILLE RH		1	enb-\$93.45
1	EMBLEM BLUE - DRIVE RH		1	100 \$35.43 100 \$26.60
	Suff da49.22.			V 1/2 \$20.00
	Carrier ussy cun / SUB TOTAL LESS 20%			\$3,605.60
	LESS 20%		3874-80	\$721.12
	DISCOUNTED TOTAL		3857.8° 3086.24	\$2,884.48
	EDT FEADER ARVERS			nv
	FRT FENDER ADVERTISEMENT LOGO RH			\$ \$100.00
				\$100.00
	Labour Charge			
	PANEL BEATING		2	~ ?
	SPRAY PAINTING CHARGE		37	\$1,050.00
	CHECK ALL LIGHTING		, 2	\$600.00
	TOTAL LABOUR		630	\$60.00
	TOTAL LABOUR	4	-	\$1,710.00
	ESTIMATE TOTAL		92716.24	
	== TOTAL		83716.24 =	\$4,694.48
			* Cons	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tunkri 97495749.
"WP' 8/4/2104phi
plp Nesny pefre pairl.
funkri c/kharbrua.
2dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is ca a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: