

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN		Ref:	CS/CTI21011383/Uvy3		
	3 ANSON ROAD #7 SPRINGLEAF TOW	1	Date:	08/11/2021		
			(	Code:	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMH 130L	Veh. Inspected		FBS 1729B	
	Policy No.	DMPCSNW00070932100	Coverage (\$)		0.00	
	Claim No.	SNM21D205613/C02/SMH130L/ CHNGPW	Excess (\$)		0.00	
	Assign From	ADELINE CHNG	Assign Date		08/11/2021	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes	Brakes Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	03/10/2021	Inspection Date	<b>;</b>	09/11/2021	
	Survey held at	Synergy @ 25 Kaki Bukit Road 4 #01-35				
	Repairer	Repairer -				
5a.		Re	Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						