

Vin's

Vin's Motor Pte Ltd
160 Sin Ming Drive
#03-03 Sin Ming Autocity
Singapore 575722
Tel : 6453 2121 Fax : 6459 9795
GST Registration No. 199906067G

Estimated Cost of Repair

Attention To : Lonpac Insurance Bhd
100 Beach Road
#19-00 Shaw Tower
Singapore 189702

Claim Details

Case Ref. No. : TP/112021/5066
Date : 08-11-2021
Accident Date : 07-11-2021

Vehicle Details

Make & Model : Toyota WISH 1.8 CVT
Chassis No : JTDGG20W70J008746
Registration No : SJN5117Y

Third Party Vehicle Details

Registration No : GBH2302A

S/N	Description	Qty	Amount (\$)
1	FRONT BONNET / BT	1.00	\$698.80
2	FRONT BONNET RH HINGE = 5 BT	1.00	\$51.03
3	FRONT BONNET LH HINGE = 5 BT	1.00	\$51.03
4	FRONT BONNET INSULATOR X 5 NN	1.00	\$390.50
5	FRONT BONNET RUBBER X BT	1.00	\$35.00
6	FRONT BONNET LOCK / BT	1.00	\$874.55
7	FRONT BONNET EMBLEM / MC	1.00	\$66.15
8	FRONT RH HEADLAMP = 5 CPA	1.00	\$1,224.80
9	FRONT LH HEADLAMP = 5 CPA	1.00	\$1,224.80
10	FRONT GRILLE / BR	1.00	\$402.10
11	FRONT BUMPER / MC	1.00	\$574.10
12	FRONT BUMPER RH FOG LAMP ?	1.00	\$208.20
13	FRONT BUMPER LH FOG LAMP ?	1.00	\$208.20
14	FRONT BUMPER RH FOG LAMP COVER ?	1.00	\$75.00
15	FRONT BUMPER LH FOG LAMP COVER ?	1.00	\$75.00
16	FRONT BUMPER RH SIDE RETAINER X NN	1.00	\$55.30
17	FRONT BUMPER LH SIDE RETAINER ?	1.00	\$55.30
18	FRONT BUMPER SPONGE ?	1.00	\$81.00
19	FRONT BUMPER REINFORCEMENT ?	1.00	\$275.20
20	FRONT BUMPER CLIPS @ \$3.00 / MC	10.00	\$30.00
21	FRONT SUPPORT PANEL / BT	1.00	\$1,171.20
22	FRONT SUPPORT PANEL TOP COVER / CPA	1.00	\$81.60
23	FRONT SUPPORT PANEL TOP COVER @ \$3.00 clips - MC	10.00	\$30.00
24	FRONT BRACE PANEL / BT	1.00	\$81.00
25	FRONT AIRCON CONDENSER / BT X NN	1.00	\$1,054.88
26	FRONT AIRCON CONDENSER FAN MOTOR X NN	1.00	\$402.10
27	FRONT AIRCON CONDENSER FAN BLADE ?	1.00	\$213.60
28	FRONT RADIATOR ?	1.00	\$1,514.00
29	FRONT RADIATOR TOP HOSE X NN	1.00	\$39.50
30	FRONT RADIATOR LOWER HOSE ?	1.00	\$60.30
31	FRONT RADIATOR RH SIDE GUIDE ?	1.00	\$61.50

Vin's

Vin's Motor Pte Ltd
 160 Sin Ming Drive
 #03-03 Sin Ming Autocity
 Singapore 575722
 Tel : 6453 2121 Fax : 6459 9795
 GST Registration No. 199906067G

32	FRONT RADIATOR LH SIDE GUIDE	1.00	\$61.50
33	FRONT RADIATOR FAN MOTOR	1.00	\$410.20
34	FRONT RADIATOR FAN BLADE	1.00	\$165.20
35	FRONT RADIATOR FAN COWLING	1.00	\$200.70
36	FRONT LH FENDER	1.00	\$775.90
37	FRONT LH FENDER INNER SHIELD	1.00	\$150.70
38	FRONT LH FENDER INNER SHIELD CLIPS @ \$3.00	1.00	\$3.00

\$13,132.94

Discount: -25%

(\$3,283.24)

\$9,849.70

39	FRONT NO. PLATE	1.00	\$40.00
40	TO REFILL AIRCON GAS	1.00	\$120.00
41	TO REPAIR DAMAGES	1.00	\$980.00
42	TO SPRAY PAINTING	1.00	\$1,100.00

Subtotal w/o GST:

\$12,089.70

6 Days.
 paint by part.
 before paint photos.
 Gmo Qianp
 09/11/21

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: