

Steve CLKK) WL PL
 LIS
 9/11/21, 5-30pm M PL M, 6 days
 Adjustment of Spare Parts Costs for Repairs SJJ 9943Z

Item	Qty	Vehicle parts description	Estimate by
		List Items	
1	1	rear bumper / DD	\$620.00 /
2	2	rear bumper side retainer / BR	\$60.00 /
3	2	rear bumper bracket ? X NN	\$48.00
4	1 set	rear bumper clips / nec	\$35.00 30 /
5	2 1	tail lamp CR(LH) / CUT	\$800.00 352 /
6	2 sets	tail lamp clips X NN	\$42.00
7	1	tail gate / DD	\$1,050.00 983 /
8	1	tail gate inner lock ? / BT	\$185.00 /
9	1	tail gate lock striker X NN	\$35.00
10	1	tail gate wiper arm X NN	\$60.00
11	1	tail gate wiper blade X NN	\$55.00
12	1	tail gate wiper motor X NN	\$288.00
13	1	tail gate weatherstrip ? / TN	\$185.00 /
14	1	tail gate honda logo X nec NN	\$85.00
15	1	tail gate stream logo X / nec	\$85.00 58 /
16	1	tail gate rsz logo emblem / nec	\$70.00 60 /
17	1	tail gate shock absorber LH X NN	\$120.00
18	1	tail gate stopper X NN	\$10.20
19	1	tail gate inner trim board ? / BR	\$280.00 /
20	1	tail gate lower pull handle X NN	\$55.00
21	1	tail gate centre garnish X NN	\$218.00
22	1	rear end panel ? / DD	\$385.00 306 /
23	1	rear end panel top garnish / BR	\$180.00 130 /
24	1	rear end panel top garnish clips / nec	\$20.00 10 /
25	1	spare tyre panel X R	\$698.00
26	2	spare tyre panel board X NN	\$558.00
27	1	rear windscreen X NN	\$1,080.00
28	2	rear windscreen glass moulding / nec	\$65.00 /
29	2	rear wind screen inner seal X NN	\$30.00
30	1	rear chassic frame X NN	\$350.00
31	2	rear fender inner trim (LH & RH) / BR	\$860.00 384 x 2 = 768 /
32	2 set	rear fender inner trim clips LH & RH / nec	\$70.00 20 /
33	1	Exhaust mounting X NN	\$93.00
34	1	towing cover / CR4	\$95.00 28 /
35	2	carplate lamps X NN	\$110.00
			<hr/>
			\$8,980.20
			4140 -20% 3312

Less 20%

\$1,796.04

\$7,184.16

Special nett item

1	1	LTA compliant whole exhaust assy	BT	\$1,500.00	800 ✓
2	1	windscreen sealant	AK	\$60.00	40 ✓
3	1	rear end panel sealant	AK	\$60.00	30 ✓
4	4	reverse sensor	shhd	\$200.00	✓
5	1	number plate w casing	X NN	\$50.00	
6	1	reverse camera	X NN	\$250.00	
7	1	insulation pad	7 X NN	\$120.00	

Total parts

\$2,240.00

1070 ✓

Adjustment of Labour Costs for Repairs

Spraying of affected areas, bootlid/ bumper/ end panel/ spare tyre panel/ fenders \$800.00 ✓

Carry out body cavity preservation \$100.00 30

To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat, rear fender LH/RH, bootlid, end panel etc \$800.00 600

Check wiring	\$50.00	30
Remove & reinstall rear windscreen	\$150.00	120
Remove & refix bootlid componets	\$80.00	50
Remove & reinstall reverse sensor	\$60.00	30
Remove & reinstall rear boot upholstery	\$80.00	50
Remove & refix exhaust	\$100.00	80
to straighten rear chassic member	\$250.00	X
Remove & refix rear seats and cushion	\$120.00	X
remove & reinstall reverse camera	\$80.00	30

Total labour

\$2,670.00

1820 ✓
= 6202

L/S - 4961-60
= 4950

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: