

Steve CLKK ML PL
 LIS
 9/11/21, 5:30pm My PL py, 6 days

Adjustment of Spare Parts Costs for Repairs SJJ 9943Z

Item	Qty	Vehicle parts description	Estimate by
List Items			
1	1	rear bumper / DD	\$620.00
2	2	rear bumper side retainer - BR	\$60.00
3	2	rear bumper bracket ?	\$48.00
4	1set	rear bumper clips - nec	\$35.00 Jo
5	2 1	tail lamp CR(LH) - CRT	\$800.00
6	2 sets	tail lamp clips X	\$42.00
7	1	tail gate / DD	\$1,050.00
8	1	tail gate inner lock nec ?	\$185.00
9	1	tail gate lock striker X	\$35.00
10	1	tail gate wiper arm X	\$60.00
11	1	tail gate wiper blade X	\$55.00
12	1	tail gate wiper motor X ?	\$288.00
13	1	tail gate weatherstrip ?	\$185.00
14	1	tail gate honda logo X nec	\$85.00
15	1	tail gate stream logo X - nec	\$85.00
16	1	tail gate rsz logo emblem - nec	\$70.00
17	1	tail gate shock absorber LH X	\$120.00
18	1	tail gate stopper X	\$10.20
19	1	tail gate inner trim board ?	\$280.00
20	1	tail gate lower pull handle X	\$55.00
21	1	tail gate centre garnish X	\$218.00
22	1	rear end panel ?	\$385.00
23	1	rear end panel top garnish - BR	\$180.00
24	1	rear end panel top garnish clips - nec	\$20.00 10
25	1	spare tyre panel X R	\$698.00
26	2	spare tyre panel board X	\$558.00
27	1	rear windscreen X	\$1,080.00
28	2	rear windscreen glass moulding - nec	\$65.00
29	2	rear wind screen inner seal X	\$30.00
30	1	rear chassic frame X	\$350.00
31	1	rear fender inner trim LH & RH - BR	\$860.00
32	2set	rear fender inner trim clips LH & RH - nec	\$70.00 20
33	1	Exhaust mounting X	\$93.00
34	1	towing cover - CR4	\$95.00
35	2	carplate lamps X	\$110.00
			<hr/>
			\$8,980.20

Less 20%

\$1,796.04

\$7,184.16

Special nett item

1	1	LTA compliant whole exhaust assy	BT	\$1,500.00	800
2	1	windscreen sealant	nk	\$60.00	40
3	1	rear end panel sealant		\$60.00	?
4	4	reverse sensor	shhd	\$200.00	✓
5	1	number plate w casing	X	\$50.00	
6	1	reverse camera	X	\$250.00	
7	1	insulation pad	?	\$120.00	

Total parts

\$2,240.00

Adjustment of Labour Costs for Repairs

Spraying of affected areas, bootlid/ bumper/ end panel/ spare tyre panel/ fenders	\$800.00	600
Carry out body cavity preservation	\$100.00	30
To remove and replaced damaged parts including straightening and repositioning replacement parts & panel beat, rear fender LH/RH, bootlid, end panel etc	\$800.00	600
Check wiring	\$50.00	30
Remove & reinstall rear windscreen	\$150.00	120
Remove & refix bootlid componets	\$80.00	50
Remove & reinstall reverse sensor	\$60.00	30
Remove & reinstall rear boot upholstery	\$80.00	50
Remove & refix exhaust	\$100.00	80
to straighten rear chassic member	\$250.00	X
Remove & refix rear seats and cushion	\$120.00	X
remove & reinstall reverse camera	\$80.00	30

Total labour

\$2,670.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: