



# HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

08 November 2021

QUOT202111-000001

TP21-57

EQ INSURANCE COMPANY LTD.

5 MAXWELL RD, #17-00  
MND COMPLEX  
SINGAPORE 069110

*Veron*

Attn: Motor Claims Department

**ACCIDENT INVOLVING SLZ7658C & SLH4279C ON 05/11/2021 BLK 219 TOA PAYOH LOR 8  
OSCP AT ABOUT 1400 HOURS**

Insured	:	HUA HONG PTE LTD
Vehicle Registration No.	:	SLZ7658C
Vehicle Make	:	TOYOTA
Vehicle Model	:	C-HR HYBRID 1.8S CVT
Vehicle Chassis No.	:	ZYX102119018
Policy No.	:	5109921641-02
Date of Accident	:	05/11/2021

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Front Bumper <i>Delud</i>		<del>\$ 2,099.00</del> <i>985</i>
2	10	Front Bumper Clips <i>new</i>	\$ 5.00	\$ 50.00 <i>30</i>
3	2	Front Bumper Side Retainer (LH/RH) <i>new</i>	\$ 297.30	\$ 594.60 <i>+</i>
4	1	Front Bumper Grille (Center) <del>Delud</del> <i>new</i>		<del>\$ 251.30</del> <i>+</i>
5	1	Front Bumper Lower <i>Delud</i>		<del>\$ 1,030.80</del> <i>359</i>
6	2	Front Bumper Garnish (LH/RH) <del>new</del> <i>new</i>	\$ 251.10	\$ 502.20 <i>+</i>
7	1	Front Bumper Reinforcement <i>new</i>		\$ 1,191.30 <i>+</i>
8	1	Front Bumper Reinforcement Arm (LH) <i>new</i>		\$ 457.00 <i>+</i>
9	1	Front Bumper Foam <i>crushed</i>		<del>\$ 449.00</del> <i>108</i>
10	1	Front Bumper Top Rubber <i>new</i>		\$ 106.80 <i>+</i>
11	1	Front Bumper Towing Cover <i>Delud</i>		<del>\$ 104.10</del> <i>45</i>
12	1	Front Number Plate Garnish <i>new</i>		\$ 242.10 <i>+</i>
13	1	Front Headlamp (LH) <i>ent</i>		<del>\$ 3,660.00</del> <i>3407</i> <i>1880</i>
14	1	Front Grille <i>new</i>		\$ 896.00 <i>+</i>
15	1	Front Grille Retainer <i>new</i>		\$ 162.30 <i>+</i>
16	1	Front Grille Base <i>new</i>		\$ 396.00 <i>+</i>
17	1	Front Grille Emblem <i>new</i>		\$ 3,347.00 <i>+</i>
				\$ 15,539.50
				Less 20%
				\$ 3,107.90
				\$ 12,431.60
18	1	Front Number Plate <i>Missing</i>	NETT	<i>35</i> \$ 35.00 <i>✓</i>
To dismantle & change front bumper, front reinforcement, front headlamp (LH). Knocking front fender (LH) and all area affected by accident				\$ 800.00 <i>500</i>
To perform wire checking				\$ 50.00 <i>30</i>

CONTINUE NEXT PAGE



# HUA HONG PRIVATE LIMITED

10 Kaki Bukit Avenue 4 #04-63 Premier@Kaki Bukit Singapore 415874  
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

## Estimate Repair List

08 November 2021

QUOT202111-000001  
TP21-57

**ACCIDENT INVOLVING SLZ7658C & SLH4279C ON 05/11/2021 BLK 219 TOA PAYOH LOR 8  
OSCP AT ABOUT 1400 HOURS**

Estimate Repair List for vehicle SLZ7658C - TOYOTA C-HR HYBRID 1.8S CVT

S/N	Quantity	Description	Unit Price S\$	Amount S\$
		To spray front bumper, front reinforcement, front fender (LH) and all affected area		\$ 800.00
			780	<del>250</del>
				\$ 14,116.60
			7% GST	\$ 988.16
			<b>Total</b>	<b>\$ 15,104.76</b>

Adrian G  
1/s 09/11/21  
03 Days

total: 3370.25  
1/s: 2.7K

2.7K

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Authorised by Claims Dept