



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL RENT-A-CAR PTE LTD BLK 1 KAKI BUKIT AVE 6 BLK C #01-56 AUTOBAY @KAKI BUKITSINGAPORE 417883 ON BEHALF OF GOLD FORTE PTE LTD			Ref: CS/TP21011412/Utf3e2 Date: 16/11/2021 Code: TP533	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	SMP 5652Y	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	09/11/2021	
2. Vehicle Particulars & Condition				
	Make & Model	HONDA SHUTTLE HYBRID (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	GP72004688	Colour	GREY
	Odometer	248366 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	185/60 R15	GRENLANDER	7 mm
	L/H Front Tyre	185/60 R15	GRENLANDER	7 mm
	R/H Rear Tyre	185/60 R15	FIRENZA	7 mm
	L/H Rear Tyre	185/60 R15	GRENLANDER	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/10/2021	Inspection Date	09/11/2021
	Survey held at	BLUWEL RENT-A CAR PTE LTD BLK 1 KAKI BUKIT AVE 6 BLK C #01-56 AUTOBAY @KAKI BUKIT SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	