

TP Budget Direct.
Xiao Chen.

SJN1811C. 2018 Sept
Mazda CX5 1998 CC
JM6KF2W7AK0228913.

Rees Bumper	Behind	1378.90. ✓
Rees Bumper Clips	an	30(SN) ✓
Rees Bumper Side Holder	x02 m	48x2=96. +
Rees Bumper	low Cover x4	22.10. +
Rees Bumper	lower Garish	=
Rees Bumper Reflector LH.	could	280.40. ✓
Rees Bumper Reinforcement	vented	686.70 ✓
Taillap LH.	x01 m	925.90. +
Tailgate Reflector LH.	x01 n	499.20. +
Mazda Logo	x4	45.90. +
CX5 Wording.	m	67 X
Reverse sensor	x02 1 piece damaged	245 x 2 = 480 245

2591 S.N: 30

201280

SJN1811C.

Panel Beating

~~400~~ 350

Spray Painting

~~500~~ 350

Wiring

790

~~50~~ 30

To remove reverse sensor

~~100~~ 60

total: 2892.80

1/s: 2.3k

0.2 Pays.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2.3K