



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: DAVID PHUA

Ref: CS/INC21011416/Gvy3e2

Date: 09/11/2022

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SBB 7373T	Veh. Inspected	SCE 2218P
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1150530-001	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	09/11/2021

2. Vehicle Particulars & Condition

Make & Model	B.M.W. 216D	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	WBA2E32090P836757	Colour	SILVER
Odometer	84632 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/55 R17	PIRELLI	6 mm
L/H Front Tyre	205/55 R17	PIRELLI	6 mm
R/H Rear Tyre	205/55 R17	PIRELLI	6 mm
L/H Rear Tyre	205/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/11/2021	Inspect Date / Time	09/11/2021 (02:00 PM)
Survey held at	1ST AUTO PRO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**