



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|--|---|-----------------|-----------------------------|------------------|
| AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924 | | | Ref: CS/AGI21011418/R1tf3e2 | Date: 21/01/2022 |
| | | | Code: AGI | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLC 6205D | Veh. Inspected | SLU 9923A | |
| Policy No. | | Coverage (\$) | 0.00 | |
| Claim No. | C10012357/EE | Excess (\$) | 0.00 | |
| Assign From | IVY RATILLA | Assign Date | 09/11/2021 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | MAZDA 3 SEDAN 1.5L SP | c.c | 1496 | |
| Engine No. | HIDDEN | Year of Reg. | 2015 | |
| Chassis No. | JM6BM42A8G0311245 | Colour | BROWN | |
| Odometer | 94151 KM | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | FAIR | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 225/45 R17 | YOKOHAMA | 6 mm | |
| L/H Front Tyre | 225/45 R17 | YOKOHAMA | 6 mm | |
| R/H Rear Tyre | 225/45 R17 | YOKOHAMA | 6 mm | |
| L/H Rear Tyre | 225/45 R17 | YOKOHAMA | 6 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 05/11/2021 | Inspection Date | 10/11/2021 | |
| Survey held at | KIAN TEONG AUTO CENTRE BLK 176 SIN MING DRIVE #01-08 SIN MING CARE SINGAPORE 575721 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | | 4 Working Days | |