

 PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0904/2021/JT
DATE : 3-Nov-21
WIP : 51849

\$9322.40.

04 Days.

Veron.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 08/11/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS AMANDA KOH TING TING
ADDRESS : 53A TAVISTOCK AVENUE
SINGAPORE 554351
TELEPHONE : HP +65 96992335
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900249336
VEHICLE NO : SMW 820 A
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 25/11/2019
ENGINE NO : CHZ C31378
CHASSIS NO : WAUZZZ8V1KA101933
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 2-Nov-21
PLACE OF ACCIDENT : CTE (CITY) BEFORE HAVELOCK EXIT



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMW 820 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	✓ ✓
2	TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	S/N \$ 280.00	✓ ✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$ 480.00	X
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 4,550.00	1000 ✓
5	TO RESPRAY REAR BUMPER, REAR LID, REAR END PANELLING, LHS REAR FENDER AND SPRAY WHEEL HOUSING.	\$ 4,500.00	1100 ✓
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,282.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMM 820 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR BUMPER <i>behind</i>	1	\$ 1,944.00	✓ 1555.20
2	REAR BUMPER FIXING PARTS <i>nee n</i>	1	\$ 193.00	+
3	REAR BUMPER ADAPTER - LH <i>Not Nec</i>	1	\$ 38.00	? X
4	REAR BUMPER TOP GUIDE SECTION - LH / RH <i>Not nec</i>	2	\$ 32.00	? X
5	REAR BUMPER LOCKING MECHANISM <i>nee n</i>	2	\$ 59.00	+
6	REAR BUMPER SPOILER <i>cut</i>	1	\$ 237.00	✓ 189.60
7	REAR LIGHT REFLECTOR - LH nee n <i>cracked</i>	1	\$ 41.00	+ 32.56
8	REAR TAIL LIGHT - INNER / OUTER <i>cut</i>	2	\$ 1,754.00	✓ 1403.20
9	REAR TAIL LIGHT TRIM - LH / RH <i>nee n</i>	2	\$ 60.00	+
10	REAR BUMPER REINFORCEMENT <i>nee n</i>	1	\$ 603.00	+
11	REAR BUMPER BRACKET - LH / RH <i>nee n</i>	2	\$ 56.00	+
12	REAR BUMPER GUIDE SECTION - LH <i>Not nec</i>	1	\$ 67.00	? X
13	REAR PARKING AID SENSOR nee n <i>damaged</i>	2	TBC	x 195.12
14	REAR LID <i>Dented</i>	1	\$ 3,404.00	✓ 2723.20
15	REAR LID ATTACHEMENT PARTS <i>nee n</i>	1	\$ 295.00	+
16	REAR LID GASKET <i>nee</i>	1	\$ 205.00	✓ 164
17	ADHESIVE <i>nee</i>	1	\$ 19.00	✓ 14.88
18	AUDI EMBLEM <i>nee</i>	1	\$ 138.00	✓ 110
19	A3 EMBLEM <i>nee</i>	1	\$ 99.00	✓ 79.04
20	REAR END PANEL <i>Not nec</i>	1	\$ 360.00	X
SUB TOTAL SPARE PARTS		:	\$ 9,604.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMW 820 A

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
21	REAR END PANEL REINFORCEMENT	1	\$ 733.00	+
22	REAR END PANEL CONNECTING PLATE - LH / RH	2	\$ 290.00	+
23	REAR NO PLATE	S/N	\$ 60.00	+
24	A / SEALANT	S/N	\$ 180.00	+
25	C / WAX	S/N	\$ 140.00	+
26	METAL FILLER POWDER	S/N	\$ 280.00	+
27	STONE CHIP	S/N	\$ 180.00	+
28	SUNDRIES		\$ 350.00	? 3.60
TOTAL SPARE PARTS		:	\$ 11,817.00	
TOTAL LABOUR CHARGES		:	\$ 10,282.00	
GRAND TOTAL		:	\$ 22,099.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King*
SURVEYED DATE : *08/11/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT