

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MOHAMAD SYAFIQ BIN MOHAMAD
 RASHID
 BLK 145 RIVERVALE DRIVE #02-531
 SINGAPORE 540145

Contact : 91868456

TP Chim.
 Veron

TAX INVOICE

Repair Code : CLM16983

Date in : 06/11/2021

Vehicle Num. : SMS359L

Model : HONDA FIT 1.3G F-PACKAGE CVT

Chassis/Eng# : GK33428178/L13B3942671

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Dehd</i>	1	890.40	<i>495</i> 890.40
REAR BUMPER CENTER GARNISH <i>crucd</i>	1	139.30	✓ 139.30
REAR BUMPER SIDE GARNISH L/R <i>crucd</i>	2	58.30	✓ 116.60
REAR BUMPER SIDE RETAINER L/R <i>crucd</i>	2	11.50	✓ 23.00
REAR END PANEL <i>Dented</i>	1	539.10	✓ 539.10
REAR END PANEL ANTENNA SENSOR <i>crucd</i>	1	85.00	✓ 85.00
REAR END PANEL BUZZLE SENSOR <i>crucd</i>	1	85.00	✓ 85.00
REAR END PANEL INNER TOP GARNISH <i>crucd</i>	1	160.80	✓ 160.80
REAR EXHAUST GASKET <i>green</i>	1	40.00	+ 40.00
REAR EXHAUST RUBBER MOUNTING <i>green</i>	2	25.00	+ 50.00
REAR FENDER INNER TRIM GARNISH L/R <i>crucd</i>	2	280.70	✓ 561.40
REAR FLOOR PANEL TOP BOARD COVER <i>Dehd</i>	1	289.80	✓ 289.80
REAR SPARE TYRE PANEL <i>Rejs</i>	1	697.00	+ 697.00
REAR TAILGATE <i>Distorted</i>	1	1080.70	<i>955</i> 1,080.70
REAR TAILGATE 'FIT' EMBLEM <i>Nu</i>	1	48.20	✓ 48.20
REAR TAILGATE INNER PULL HANDLE <i>Dehd</i>	1	18.20	✓ 18.20
REAR TAILGATE INNER RUBBER SIDE GUIDE STOPPER L/R <i>green</i>	2	10.50	✓ 21.00
REAR TAILGATE INNER TRIM <i>crucd</i>	1	138.70	✓ 138.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

MOHAMAD SYAFIQ BIN MOHAMAD
RASHID
BLK 145 RIVERVALE DRIVE #02-531
SINGAPORE 540145

Contact : 91868456

TAX INVOICE

Repair Code : CLM16983

Date in : 06/11/2021

Vehicle Num. : SMS359L

Model : HONDA FIT 1.3G F-PACKAGE CVT

Chassis/Eng# : GK33428178/L13B3942671

REAR TAILGATE LOCK STRIKER	New	1	27.50	✓	27.50
REAR TAILGATE MECHANISM LOCK	Damaged	1	88.90	✓	88.90
REAR TAILGATE WEATHER STRIP	LT	1	92.30	✓	92.30
REAR TAILGATE WINDSCREEN MOULDIING	New	1	95.60	✓	95.60
REAR TAILLAMP L/R	Cracked	2	295.75	✓	591.50
REAR TOOL SPONGE TRAY	Torn	1	220.00	✓	220.00
Subtotal before discount					6,100.00
Percentage discount 20%					1,220.00
Sub-total 1					4,880.00
REAR BUMPER CLIPS - SET	New	1	50.00	✓	50.00
REAR BUMPER LOWER SPOILER	Cracked	1	800.00	500.00	800.00
REAR BUMPER REVERSE SENSOR - SET	Damaged	1	250.00	200.00	250.00
REAR BUMPER STICKER	New	1	150.00	40.00	150.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET	New	1	20.00	10.00	20.00
REAR EXHAUST SILENCER BOX	Not Repaired bent	1	1600.00	200 (LR)	1,600.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	New	2	30.00	✓	60.00
REAR NUMBER PLATE	New	1	25.00	✓	25.00
REAR NUMBER PLATE HOLDER	Damaged	1	50.00	30.00	50.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

MOHAMAD SYAFIQ BIN MOHAMAD
 RASHID
 BLK 145 RIVERVALE DRIVE #02-531
 SINGAPORE 540145

Contact : 91868456

TAX INVOICE

Repair Code : CLM16983

Date in : 06/11/2021

Vehicle Num. : SMS359L

Model : HONDA FIT 1.3G F-PACKAGE CVT

Chassis/Eng# : GK33428178/L13B3942671

REAR SPARE TYRE PANEL INSULATOR MAT	1225	1	300.00	300.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET		1	50.00	50.00
REAR TAILGATE WINDSCREEN SEALANT		1	80.00	80.00
Subtotal before discount				3,435.00
Percentage discount 0%				0.00
Sub-total 2				3,435.00
Parts-total				8,315.00

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	3,130.00
Parts & Labour Total	11,445.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*** This is a computer-generated document which requires no signature.***

page 3

Admin Lj
 h/s 09/11/21

07 Days.

Total: 7116.52

4/5 = 5.6K ✓