

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0895/2021/KS
DATE : 2-Nov-21
WIP : 51753

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/10/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR MARGANET TEOH WEI LING
ADDRESS : 29 JURONG WEST ST 41
#01-14
SINGAPORE 649411
TELEPHONE : HP +65 94758155
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100508372-04
VEHICLE NO : **SLN 2389 A**
MODEL CODE : A4 SEDAN 1.4 TFSI
MODEL YEAR : 26/4/2017
ENGINE NO : CVN 032589
CHASSIS NO : WAUZZZF45HA122027
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 30-Oct-21
PLACE OF ACCIDENT : 60 JURONG WEST ST 41, SG 649407

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 2389 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR'S AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00	560 ✓
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00	✓ ✓
3	TO PUT ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	? ✓
4	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, REAR SEATS ASSY, ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG.	S/N \$ 2,400.00	✓ ✓
5	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR, TO CUT OUT AND WELD LHS B-PILLAR AND LHS SILL PANEL. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,250.00	3000 4250
6	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, DOOR ENTRANCES, LHS REAR FENDER, LHS B-PILLAR AND LHS SILL PANEL.	\$ 5,000.00	2830 ✓ 5 x 550 = 2750 Handle = 80 2830
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		\$ 16,742.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 2389 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	SECTIONAL PART - SIDE MEMBER LH <i>Dented</i>	1	\$ 2,174.00	✓ 1739.20
2	SILL TRIM STRIP - LH <i>new</i>	1	\$ 120.00	✓ 96.00
3	FRONT DOOR - LH <i>Distorted</i>	1	\$ 3,192.00	✓ 2553.60
4	FRONT DOOR OUTER SEAL - LH <i>new</i>	1	\$ 205.00	✓ 164.00
5	BONDING AGENT ?	1	\$ 49.00	? X
6	CLEANING SOLUTION ?	1	\$ 68.00	? X
7	APPLICATOR ?	1	\$ 8.00	? X
8	FRONT DOOR ATTACHMENT PARTS - LH <i>new</i>	1	TBC	X
9	FRONT DOOR CATCH - LH ?	1	\$ 105.00	? X
10	REAR DOOR - LH <i>Distorted</i>	1	\$ 3,192.00	✓ 2553.60
11	REAR DOOR OUTER SEAL - LH <i>new</i>	1	\$ 205.00	✓ 164.00
12	BONDING AGENT ?	1	\$ 49.00	? X
13	CLEANING SOLUTION ?	1	\$ 68.00	? X
14	APPLICATOR ?	1	\$ 8.00	? X
15	SEALING STRIP ?	1	\$ 17.00	? X
16	REAR DOOR ATTACHMENT PART - LH <i>new</i>	1	\$ 860.00	X
17	REAR DOOR CATCH - LH ?	1	\$ 120.00	? 96.00
18	REAR DOOR HINGE HALF - LH UPPER PART ? <i>Bent</i>	1	\$ 44.00	✓ 34.48
19	REAR DOOR HINGE HALF - LH UPPER PART <i>Bent</i>	1	\$ 46.00	✓ 35.84
20	REAR DOOR HINGE HALF - LH LOWER PART <i>Bent</i>	1	\$ 46.00	✓ 36.40
TOTAL SPARE PARTS		:	\$ 10,576.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED



55 LBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 2389 A

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR DOOR HINGE HALF - LH LOWER PART <i>Best</i>	1	\$ 46.00	✓ 36.40
22	REAR DOOR SEAL, INNER - LH <i>at</i>	1	\$ 222.00	✓ 177.60
23	REAR DOOR TRIM PLATE FOR DOOR HANDLE <i>cracked</i>	1	\$ 88.00	✓ 69.92
24	REAR DOOR HANDLE HOUSING - LH <i>Hot ?</i>	1	\$ 8.00	? 5.92
25	REAR DOOR MOUNTING BAR - LH ?	1	\$ 164.00	? 130.80
26	REAR WINDOW REGULATOR - LH ?	1	\$ 282.00	? 225.60
27	REAR WINDOW REGULATOR MOTOR - LH ?	1	\$ 338.00	? 270.40
28	REAR DOOR CONTROL UNIT - LH ?	1	\$ 751.00	? X
29	REAR DOOR PANEL - LH ?	1	\$ 1,792.00	? X
30	REAR DOOR WIRING HARNESS - LH ?	1	\$ 297.00	? X
31	REAR DOOR WIRING SET - LH ?	1	\$ 374.00	? 298.80
32	AIRBAG STICKER <i>New</i>	1	\$ 24.00	✓ 19.04
33	FRONT WINDOW SLOT SEAL - LH <i>New</i>	1	\$ 307.00	X
34	REAR WINDOW SLOT SEAL - LH ?	1	\$ 366.00	? 292.40
35	TRIM STRIP FOR WINDOW - LH <i>New</i>	1	\$ 257.00	✓
36	TRIM STRIP FOR WINDOW - LH	1	\$ 237.00	✓
37	B- PILLAR TRIM, GLOSSY BLACK - LH ?	1	\$ 228.00	? X
38	B- PILLAR TRIM, GLOSSY BLACK - LH ?	1	\$ 147.00	? 119.20
39	C- PILLAR TRIM, GLOSSY BLACK - LH ?	1	\$ 142.00	? 113.60
40	ARCYLIX SEALANT ?	S/N	\$ 180.00	✓ 180
41	CAVITY WAX <i>New</i>	S/N	\$ 140.00	✓ 140
42	STONE CHIP	S/N	\$ 180.00	✓ 180
43	METAL FILLER POWDER <i>New</i>	S/N	\$ 280.00	✓ 280
40	SUNDRIES ?	1	\$ 450.00	? 53.44
TOTAL SPARE PARTS		:	\$ 17,876.00	
TOTAL LABOUR CHARGES		:	\$ 2,400.00	
GRAND TOTAL		:	\$ 20,276.00	

34,618.00

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian King.*
SURVEYED DATE : *02/11/21*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 11 Days.*

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: