

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 2389 A

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR'S AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 700.00	560.
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$ 800.00	✓
3	TO PUT ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$ 2,400.00	?
4	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, REAR SEATS ASSY. ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG.	S/N \$ 2,400.00	✓
5	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS B-PILLAR AND LHS SILL PANEL. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,250.00	3000. +1250 flg. +500 rear fender.
6	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, DOOR ENTRANCES, LHS REAR FENDER, LHS B-PILLAR AND LHS SILL PANEL.	\$ 5,000.00	2830 5x550 = 2750 Handle = 80
6	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$ 192.00	✓ 2830
TOTAL LABOUR CHARGES		\$ 16,742.00	

Car-in 15/11/21

wp-51753

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Bent / Hong



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 2389 A

AIG - Adrian
- 11 days

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	SECTIONAL PART - SIDE MEMBER LH <i>Dented</i>	1	\$ 2,174.00	✓
2	SILL TRIM STRIP - LH <i>New</i>	1	\$ 120.00	✓
3	FRONT DOOR - LH <i>Distorted</i>	1	\$ 3,192.00	✓
4	FRONT DOOR OUTER SEAL - LH <i>New</i>	1	\$ 205.00	✓
5	BONDING AGENT ?	1	\$ 49.00	?
6	CLEANING SOLUTION ?	1	\$ 68.00	?
7	APPLICATOR ?	1	\$ 8.00	?
8	FRONT DOOR ATTACHMENT PARTS - LH <i>New</i>	1	TBC	X
9	FRONT DOOR CATCH - LH ?	1	\$ 105.00	?
10	REAR DOOR - LH <i>Distorted</i>	1	\$ 3,192.00	✓
11	REAR DOOR OUTER SEAL - LH <i>New</i>	1	\$ 205.00	✓
12	BONDING AGENT ?	1	\$ 49.00	?
13	CLEANING SOLUTION ?	1	\$ 68.00	?
14	APPLICATOR ?	1	\$ 8.00	?
15	SEALING STRIP ?	1	\$ 17.00	?
16	REAR DOOR ATTACHMENT PART - LH <i>New</i>	1	\$ 860.00	X
17	REAR DOOR CATCH - LH <i>Dmgd</i>	1	\$ 120.00	✓
18	REAR DOOR HINGE HALF - LH UPPER PART ? <i>Bent</i>	1	\$ 44.00	✓
19	REAR DOOR HINGE HALF - LH UPPER PART <i>Bent</i>	1	\$ 46.00	✓
20	REAR DOOR HINGE HALF - LH LOWER PART <i>Bent</i>	1	\$ 46.00	✓
TOTAL SPARE PARTS			\$ 10,576.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

Add

8KO 837 199 X 8

Adrian Lj
Slip 16/11/21



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 2389 A

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
21	REAR DOOR HINGE HALF - LH LOWER PART <i>Best</i>	1	\$ 46.00	✓	
22	REAR DOOR SEAL, INNER - LH <i>at</i>	1	\$ 222.00	✓	
23	REAR DOOR TRIM PLATE FOR DOOR HANDLE <i>cracked</i>	1	\$ 88.00	✓	
24	REAR DOOR HANDLE HOUSING - LH <i>not Dmg</i>	1	\$ 8.00	✓	
25	REAR DOOR MOUNTING BAR - LH <i>Dmg</i>	1	\$ 164.00	✓	
26	REAR WINDOW REGULATOR - LH <i>Dmg</i>	1	\$ 282.00	✓	
27	REAR WINDOW REGULATOR MOTOR - LH <i>Dmg</i>	1	\$ 338.00	✓	
28	REAR DOOR CONTROL UNIT - LH ?	1	\$ 751.00	?	
29	REAR DOOR PANEL - LH ?	1	\$ 1,792.00	?	
30	REAR DOOR WIRING HARNESS - LH ?	1	\$ 297.00	?	
31	REAR DOOR WIRING SET - LH <i>Snapped</i>	1	\$ 374.00	✓	
32	AIRBAG STICKER <i>new</i>	1	\$ 24.00	✓	
33	FRONT WINDOW SLOT SEAL - LH <i>not in</i>	1	\$ 307.00	X	
34	REAR WINDOW SLOT SEAL - LH ?	1	\$ 366.00	?	
35	TRIM STRIP FOR WINDOW - LH <i>new</i>	1	\$ 257.00	✓	
36	TRIM STRIP FOR WINDOW - LH	1	\$ 237.00	✓	
37	B- PILLAR TRIM, GLOSSY BLACK - LH ?	1	\$ 228.00	?	
38	B- PILLAR TRIM, GLOSSY BLACK - LH	1	\$ 147.00	?	
39	C- PILLAR TRIM, GLOSSY BLACK - LH ?	1	\$ 142.00	?	
40	ARCYLIX SEALANT ?	S/N	\$ 180.00	✓	
41	CAVITY WAX <i>new</i>	S/N	\$ 140.00	✓	
42	STONE CHIP	S/N	\$ 180.00	✓	
43	METAL FILLER POWDER <i>new</i>	S/N	\$ 280.00	✓	
40	SUNDRIES ?	1	\$ 450.00	?	
TOTAL SPARE PARTS			:	\$ 17,876.00	
TOTAL LABOUR CHARGES			:	\$ 2,400.00	
GRAND TOTAL			:	\$ 20,276.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED