



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0895/2021/KS  
DATE : 02-Nov-21  
WIP : 51753

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 7/10/21

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

Hi Adrian,

15 days - ok - Jy - 23 Feb 22

OWNER'S NAME : MR MARGANET TEOH WEI LING  
ADDRESS : 29 JURONG WEST ST 41  
#01-14  
SINGAPORE 649411  
TELEPHONE : HP +65 94758155  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO : 2100508372-04  
VEHICLE NO : SLN 2389 A  
MODEL CODE : A4 SEDAN 1.4 TFSI  
MODEL YEAR : 26/04/2017  
ENGINE NO : CVN 032589  
CHASSIS NO : WAUZZZF45HA122027  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 30-Oct-21  
PLACE OF ACCIDENT : 60 JURONG WEST ST 41, SG 649407

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLN 2389 A**

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER LHS FRONT DOOR'S AND LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$	700.00	\$	560.00
2	TO CARRY OUT FIRST MEASUREMENT TEST ON CAR-O-LINER.	S/N \$	800.00	\$	800.00
3	TO PUT ON THE VEHICLE ON CAR-O-LINER TO FACILITATE THE REPAIR.	S/N \$	2,400.00	\$	2,400.00
4	TO REMOVE AND REINSTALL LHS FRONT SEAT ASSY, REAR SEATS ASSY. ABCD PILLAR TRIMS, SILL TRIMS, FLOOR CARPETS, ELECTRONIC COMPONENTS AND FUSE TRAYS. DISENGAGE LHS SEAT BELT AND HEAD AIRBAG.	S/N \$	2,400.00	\$	2,400.00
5	TO DISMANTLE AND RENEW LHS FRONT DOOR AND LHS REAR DOOR. TO CUT OUT AND WELD LHS B-PILLAR AND LHS SILL PANEL. TO REPAIR LHS REAR FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	5,250.00	\$	4,250.00
6	TO RESPRAY LHS FRONT DOOR, LHS REAR DOOR, DOOR HANDLES, DOOR ENTRANCES, LHS REAR FENDER, LHS B-PILLAR AND LHS SILL PANEL.	\$	5,000.00	\$	2,830.00
7	SUPPLEMENTARY	\$	280.00	\$	280.00
8	TO CARRY OUT DIAGNOSTIC CHECK	S/N \$	192.00	\$	192.00
<b>TOTAL LABOUR CHARGES</b>		<b>:</b>	<b>\$ 17,022.00</b>	<b>\$</b>	<b>13,712.00</b>



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 2389 A**

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	SECTIONAL PART - SIDE MEMBER LH	1	\$ 2,174.00	\$ 1,739.20
2	SILL TRIM STRIP - LH	1	\$ 120.00	\$ 96.00
3	FRONT DOOR - LH	1	\$ 3,192.00	\$ 2,553.60
4	FRONT DOOR OUTER SEAL - LH	1	\$ 205.00	\$ 164.00
5	BONDING AGENT	1	\$ 49.00	
6	CLEANING SOLUTION	1	\$ 68.00	
7	APPLICATOR	1	\$ 8.00	
8	FRONT DOOR ATTACHMENT PARTS - LH	1	TBC	
9	FRONT DOOR CATCH - LH	1	\$ 105.00	
10	REAR DOOR - LH	1	\$ 3,192.00	\$ 2,553.60
11	REAR DOOR OUTER SEAL - LH	1	\$ 205.00	\$ 164.00
12	BONDING AGENT	1	\$ 49.00	
13	CLEANING SOLUTION	1	\$ 68.00	
14	APPLICATOR	1	\$ 8.00	
15	SEALING STRIP	1	\$ 17.00	
16	REAR DOOR ATTACHMENT PART - LH	1	\$ 860.00	
17	REAR DOOR CATCH - LH	1	\$ 120.00	\$ 96.00
18	REAR DOOR HINGE HALF - LH UPPER PART	1	\$ 44.00	\$ 34.48
19	REAR DOOR HINGE HALF - LH UPPER PART	1	\$ 46.00	\$ 35.84
20	REAR DOOR HINGE HALF - LH LOWER PART	1	\$ 46.00	\$ 36.40
<b>TOTAL SPARE PARTS</b>		<b>:</b>	<b>\$ 10,576.00</b>	<b>\$ 7,473.12</b>

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND:      REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLN 2389 A**

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
				\$	7,473.12
21	REAR DOOR HINGE HALF - LH LOWER PART	1	\$	46.00	\$ 36.40
22	REAR DOOR SEAL , INNER - LH	1	\$	222.00	\$ 177.60
23	REAR DOOR TRIM PLATE FOR DOOR HANDLE	1	\$	88.00	\$ 69.92
24	REAR DOOR HANDLLE HOUSING - LH	1	\$	8.00	\$ 5.92
25	REAR DOOR MOUNTING BAR - LH	1	\$	164.00	\$ 130.80
26	REAR WINDOW REGULATOR - LH	1	\$	282.00	\$ 225.60
27	REAR WINDOW REGULATOR MOTOR - LH	1	\$	338.00	\$ 270.40
28	REAR DOOR CONTROL UNIT - LH	1	\$	751.00	
29	REAR DOOR PANEL - LH	1	\$	1,792.00	
30	REAR DOOR WIRING HARNESS - LH	1	\$	297.00	
31	REAR DOOR WIRING SET - LH	1	\$	374.00	\$ 298.80
32	AIRBAG STICKER	1	\$	24.00	\$ 19.04
33	FRONT WINDOW SLOT SEAL - LH	1	\$	307.00	
34	REAR WINDOW SLOT SEAL - LH	1	\$	366.00	\$ 292.40
35	TRIM STRIP FOR WINDOW - LH	1	\$	257.00	
36	TRIM STRIP FOR WINDOW - LH	1	\$	237.00	
37	B- PILLAR TRIM, GLOSSY BLACK - LH	1	\$	228.00	
38	B- PILLAR TRIM, GLOSSY BLACK - LH	1	\$	147.00	\$ 119.20
39	C- PILLAR TRIM, GLOSSY BLACK - LH	1	\$	142.00	\$ 113.60
40	ARCYLIX SEALANT	S/N	\$	180.00	\$ 180.00
41	CAVITY WAX	S/N	\$	140.00	\$ 140.00
42	STONE CHIP	S/N	\$	180.00	\$ 180.00
43	METAL FILLER POWDER	S/N	\$	280.00	\$ 280.00
44	SUPPLEMENTARY		\$	1,728.00	\$ 1,382.56
45	SUNDRIES	1	\$	450.00	\$ 53.44
<b>TOTAL SPARE PARTS</b>		:	\$	<b>19,604.00</b>	\$ 11,448.80
<b>TOTAL LABOUR CHARGES</b>		:	\$	<b>2,400.00</b>	\$ 13,712.00
<b>GRAND TOTAL</b>		:	\$	<b>22,004.00</b>	\$ 25,160.80

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED



55 Ubi Road 1, Singapore 408699  
 Tel : 6366 2323 Fax : 6841 1183  
 Email Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**Supplementary Estimate-1**

GST Reg No. 19-9902271-W

<b>AIG Asia Pacific Insurance Pte Ltd</b>	<b>Estimate No.</b>	PA/OD/0895/2021/KS
78 Shenton Way	<b>Date</b>	16-Nov-21
#07-16 AIG Building	<b>Service Advisor</b>	CHANG
Singapore 079120	<b>Pages</b>	1 of 1
Attn: Mr. Adrian Ling - Motor Claims Dept	<b>Regn No</b>	SLN 2389 A
<b>Tel: 6841 0055 / Fax: 6256 4315</b>	<b>Model No</b>	AUDI A4 SEDAN 1.4 TFSI

Quantity	Description	Unit Price	Amount
----------	-------------	------------	--------

**Labours :**

1	TO RECTIFY AND RENEW DAMAGE WIRE, CHECK ELECTRIC SYSTEM AND FUNCTION.	S/N	\$ 280.00	\$ 280.00
---	--------------------------------------------------------------------------	-----	-----------	-----------

**Parts**

1	BASS LOUDSPEAKER - LH REAR		\$ 141.00	\$ 112.80
2	REAR DOOR WIRING HARNESS CONNECTOR		\$ 17.00	\$ 13.60
3	REAR DOOR LOCK - LH		\$ 661.00	\$ 528.40
4	REAR DOOR UNDERLAY - LH REAR		\$ 4.00	\$ 2.88
5	REAR DOOR UNDERLAY - LH FRONT		\$ 4.00	\$ 2.88
6	REAR DOOR HANDLE, EXTERIOR - LH		\$ 44.00	\$ 37.28
7	REAR DOOR HANDLE SENSOR - LH		\$ 228.00	\$ 182.40
8	REAR DOOR HANDLE PERIPHERAL LIGHT - LH		\$ 72.00	\$ 57.28
9	REAR DOOR HANDLE TRANSPARENT COVER - LH		\$ 6.00	\$ 4.64
10	B-PILLAR PANLE - LH INNER		\$ 551.00	\$ 440.40

<b>GRAND TOTAL</b>	<b>\$ 2,008.00</b>	<b>\$ 1,662.56</b>
--------------------	--------------------	--------------------

For Premium Automobiles Pte Ltd

\_\_\_\_\_  
 Authorised Signature



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT