



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD		Ref:	CS3/LPC21008526/R1qf3e2-1
300 BEACH ROAD		Date:	06/06/2022
#17-04/07 THE CONCOURSESINGAPORE 199555		Code:	LPC2
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBD 8184E	Veh. Inspected	GBE 6506T
Policy No.		Coverage (\$)	0.00
Claim No.	21/21/21/VC05/024843	Excess (\$)	0.00
Assign From	KENNY LIM	Assign Date	09/11/2021
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA HIACE 3.0DX M	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KDH2010184423	Colour	GREY
Odometer	205152 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195 R15C	DUNLOP	6 mm
L/H Front Tyre	195 R15C	DUNLOP	6 mm
R/H Rear Tyre	195 R15C	DUNLOP	6 mm
L/H Rear Tyre	195 R15C	DUNLOP	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/08/2021	Inspection Date	16/08/2021
Survey held at	WILLY MOTOR COMPANY 27A JURONG PORT ROAD #01-32 SINGAPORE 619101		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR (FRONT):		4 Working Days	
ESTIMATED NORMAL PERIOD FOR REPAIR (REAR):		6 Working Days	