


ASS. F. BY:

REF: CC4 GRB 21011432 Des³

ASSIGNMENT

From: _____ Date: _____
Estimate Cost: _____
CD / F / W / P / RES / DD RES / EVA / INV / MV
To Inspect Vehicle No: _____
at V/O of _____ m/s
of _____
Insurance _____
Policy No. _____
Claims to _____
Sum Insured: _____ Excess: _____
(Check record)
Make & Model: _____

Veh No: FBP 8307 E Yr Reg: Jun / 2019
Type: MCar / MCycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or _____
Make: Yamaha GDR155A cc 155
Colour: Black / white A/C: Insured / Std / NA
Sp. Reading: 45120 T/Ratio: Insured / Std / NA
Eng/No: G3J88E0104812
C/No: M+13SG4640KJ055919
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Mod: RE / STD / STD A/R or
Tyre Size: F: 120/70 R14
R: 140/60 R14
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUEZI /
TOYO / YOKO or Michelin



(Policy Condition)
Remark: The veh had commented its
repair at the time of inspection.
Bal. of Market Value: _____
IDAC Accident Report _____ Consistent? : Yes or No
GIA / PR Seat: _____ Consistent? : Yes or No
Est. Repairs: 1 days Res.: Yes or No
Limit Sum: P/P % 3 Val: Yes or No

Front _____ Rear _____
R/Bal: 2 mm R/Bal: 2 mm
L/Bal: _____ mm L/Bal: _____ mm
D.O.A: 06/11/21 D.O.L: 10/11/21
Survey held at SG 98 AMIC
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Roof or
Rear

CA / REV / REP. / 24 HRS
Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>III SMQ 2442B</u>
<u>14/04/22</u>	<u>Insured TLP 258-w with 1 day 2 reg</u>

SG 98 MOTOR PTE LTD

4001, Ang Mo Kio Industrial Park 1 #01-21 SINGAPORE 569622

Tel: 6452 4898 Fax: 6452 4868

Email: sg_motor_enterprise@yahoo.com.sg

Date: 10 November 2021

To : LKK

By Fax: 6256-4315

Attn : Bryan

Tel : 97237799

VEHICLE NO : FBP 8307E

Aerox 155

ACCIDENT DATE: 6 November 2021

Description	Qty	Quotation \$
1 Rear Mudguard <i>distorted/damaged</i>	1	220.00 ✓
2 Number Plate Holder <i>2pc</i>	1	80.00 X
3 Exhaust Pipe <i>rep</i>	1	580.00 X
Sub-Total		0.00 880.00
Less 10%		0.00 88.00
Sub-Total		0.00 792.00

Nett items

1 Labour charge	150.00 60/-
Sub-Total	150.00
Nett Total	150.00 942.00

NB: This estimate was made from a visual inspection only, any other damage parts or labour require when repair commences, we will advise you and submit supplementary item to you accordingly.

Kindly revert upon completion. Thank you

7/7 258.00

1 day.

SG 98 MOTOR PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10/11/2021 @ 1200hrs

Not Attached

7/7 258.00

1 day

Signature

LKK Auto