

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel: 62898126 Fax : 62870590

Email: Jin@jinauto.com.sg

Company Reg No:200704370C GST Reg No :200704370C

17/11/2021

M/S AIG

DEAR SIR/MADAM

ESTIMATE REPAIR COST FOR TOYOTA HIACE - GBE7414T

DOA : 06/11/2021

S/N	QTY	DESCRIPTION			
1		SPRAY PAINTING	\$	880.00	600
2		LABOUR CHARGE	\$	380.00	200
3		ARTWORK	\$	380.00	X
Total			\$	<u>1640.00</u>	

not Allowed
LCC
the ph. After open
18/11/21
P/P \$ 800
2 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: