



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:YVONNE			Ref: CC4/ASM21011437/Apa3q2 Date: 04/05/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 7726T	Veh. Inspected	SLR 5619X	
Policy No.	P2426680	Coverage (\$)	0.00	
Claim No.	S1M03LK4	Excess (\$)	0.00	
Assign From		Assign Date	09/11/2021	
2. Vehicle Particulars & Condition				
Make & Model	MAZDA 5	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JM6CW1071H0126281	Colour	BLACK	
Odometer	54150 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Front Tyre	205/55 R16	YOKOHAMA	6 mm	
R/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
L/H Rear Tyre	205/55 R16	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	05/11/2021	Inspection Date	09/11/2021	
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	