

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

ANANTHANARAYANAN
 VENKATASUBRAMANIAN
 10 GEYLANG EAST AVE 2 #09-09 SIMSVILLE
 SINGAPORE 389758

Contact : 91172591

TPAXA-
 Asher.

TAX INVOICE

Repair Code : CLM16985

Date in : 08/11/2021

Vehicle Num. : SLR5619X

Model : MAZDA5 WAGON 2.0 AT EU6

Chassis/Eng# : JM6CW1071H0126281/PE10522221

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>delnd</i>	1	961.00	✓ 961.00
REAR BUMPER CENTER CLIPS <i>new</i>	2	6.20	✓ 12.40
REAR BUMPER REFLECTOR COVER L/R <i>LH could</i>	2	21.60	<i>21.60</i> 43.20
REAR BUMPER REFLECTOR L/R <i>LH could</i>	2	53.00	<i>53</i> 106.00
REAR BUMPER REINFORCEMENT <i>delnd</i>	1	175.00	✓ 175.00
REAR BUMPER SIDE BRACKET L/R <i>new</i>	2	31.20	+ 62.40
REAR BUMPER SIDE BRACKET RIVET L/R <i>new</i>	4	5.90	+ 23.60
REAR BUMPER SIDE RETAINER L/R <i>delnd</i>	2	47.60	✓ 95.20
REAR END PANEL <i>Regis</i>	1	545.00	+ 545.00
REAR END PANEL INNER TOP GARNISH <i>delnd</i>	1	109.00	✓ 109.00
REAR EXHAUST GASKET <i>new</i>	1	12.60	+ 12.60
REAR EXHAUST HEAT COVER <i>crushed</i>	1	79.00	✓ 79.00
REAR EXHAUST RUBBER MOUNTING <i>new</i>	2	23.00	+ 46.00
REAR EXHAUST SILENCER BOX <i>Regis</i>	1	1109.00	+ 1,109.00
REAR FENDER INNER SHIELD L/R <i>LH ut</i>	2	45.00	<i>45</i> 90.00
REAR TAILGATE <i>delnd</i>	1	1637.00	✓ 1,637.00
REAR TAILGATE 'LOGO' EMBLEM <i>3 new</i>	1	44.10	✓ 44.10
REAR TAILGATE 'MAZDA 5' EMBLEM	1	36.80	✓ 36.80

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANANTHANARAYANAN
VENKATASUBRAMANIAN
10 GEYLANG EAST AVE 2 #09-09 SIMSVILLE
SINGAPORE 389758

Contact : 91172591

TAX INVOICE

Repair Code : CLM16985

Date in : 08/11/2021

Vehicle Num. : SLR5619X

Model : MAZDA5 WAGON 2.0 AT EU6

Chassis/Eng# : JM6CW1071H0126281/PE10522221

REAR TAILGATE 'SKYACTIV' EMBLEM <i>Nec</i>	1	80.00	✓	80.00
REAR TAILGATE HINGES L/R <i>Nec</i>	2	38.60	+	77.20
REAR TAILGATE INNER RUBBER GUIDE STOPPER L/R <i>Nec</i>	2	10.60	+	21.20
REAR TAILGATE LOCK STRIKER <i>Nec</i>	1	48.00	+	48.00
REAR TAILGATE MECHANISM LOCK <i>Nec</i>	1	286.00	+	286.00
REAR TAILGATE WEATHER STRIP <i>Nec</i>	1	177.50	✓	177.50
REAR TAILGATE WINDSCREEN MOULDING <i>Nec</i>	1	105.00	✓	105.00
REAR TAILGATE WINDSCREEN SEAL <i>Nec</i>	1	90.00	✓	90.00
Subtotal before discount				6,072.20
Percentage discount 20%				1,214.44
Sub-total 1				4,857.76
REAR BUMPER CLIPS - SET <i>Nec</i>	1	80.00	30	80.00
REAR BUMPER REVERSE SENSOR - SET <i>Nec</i>	1	280.00	200	280.00
REAR BUMPER TOP RUBBER SEAL <i>Nec</i>	1	250.00	150	250.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>Nec</i>	1	50.00	10	50.00
REAR TAILGATE NUMBER PLATE <i>Nec</i>	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE HOLDER <i>Nec</i>	1	50.00	+	50.00
REAR TAILGATE WINDSCREEN SEALANT <i>Nec</i>	1	80.00	60	80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

ANANTHANARAYANAN
VENKATASUBRAMANIAN
10 GEYLANG EAST AVE 2 #09-09 SIMSVILLE
SINGAPORE 389758

Contact : 91172591

TAX INVOICE

Repair Code : CLM16985

Date in : 08/11/2021

Vehicle Num. : SLR5619X

Model : MAZDA5 WAGON 2.0 AT EU6

Chassis/Eng# : JM6CW1071H0126281/PE10522221

Subtotal before discount	815.00
Percentage discount 0%	0.00
Sub-total 2	815.00
Parts-total	5,672.76

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the rear bootlid, rear end panel, rear fender (L/R), spare tyre panel and rear bumper.

To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

Labour Total	2,650.00
Parts & Labour Total	8,322.76

✓ 80.00
120 150.00
50 120.00
600 1,000.00
80 100.00
60 1,000.00
50 120.00
60 80.00

1650

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Adrian Lij
H/S 09/11/21

05 Days

total: 5077.28
H/S: 41C ✓