

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

not Authorized
date
9/11/21
1/5 \$3200
3 days.

VEHICLE No: SLH 3893K

1PC	BONNET	20/2ert	1037.30	\$1,087.30
1PC	BONNET INNER RUBBER	11		\$68.00 X
1PC	BONNET INSULATOR	11		\$285.20 X
1SET	BONNET INSULATOR CLIPS	11		\$50.00 X
1PC	FRONT GRILLE	11		\$466.01 X
1PC	HEADLAMP O/S	one	822.30	\$1,280.10
1PC	FRONT BUMPER	repcant	483.60	\$588.10
1PC	FRONT BUMPER BEAM	11		\$419.80 X
1PC	FRONT BUMPER SPONGE	11		\$98.80 X
1PC	FRONT BUMPER FOG LAMP O/S	11		\$315.40 X
1PC	FRONT BUMPER FOG LAMP COVER O/S	grated		\$98.50
1PC	FRONT BUMPER SIDE RETAINER O/S	self		\$75.20
1SET	FRONT BUMPER CLIPS	rec		\$50.00
1PC	FRONT SUPPORT PANEL	R		\$899.50 X
1PC	FRONT FENDER O/S	20/2ert		\$745.20
1PC	FRONT FENDER INNER SHIELD O/S	11		\$188.50 X
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	rec		\$50.00
1PC	FRONT FENDER 'VVTI' EMBLEM O/S	rec		\$68.10
1PC	WIPER WASHER TANK	svc	257	\$184.20 X
				\$7,017.91

TO CHECK WIRING
TO SPRAY RUST PROOFING
TO RESET & REPROGRAMME SYSTEM
TO REFILL AIR CON GAS
LABOUR FOR PANEL BEATING & REPLACED PARTS
TO PUTTY & SPRAY PAINTING

\$50.00 20
\$80.00 60
\$180.00 50
11 \$120.00 X
\$750.00 540
\$980.00 800
TOTAL \$9,177.91

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1-343040
252
1-2572.60
1-1470
4043.80
202
3204