

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 26/11/2021

User ID                      PohSuan

**Section A - Accident Details**

Registration Number	SHB598L
Case Reference Number	TAX/11/21/2007
Registration Date	12/10/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	HO CHIN KEONG
Type of Accident	Side Swipe
Accident Date and Time	6/11/2021 7:45 PM
Accident Reported Date and Time	8/11/2021 8:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24112944
Special Instruction to ARC, if any	BP/ RIGHT FRONT PORTION / DROVE IN/CHINA TAIPING - LKK
Prepared Date and Time	8/11/2021 5:51 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$507.00	\$200.00
Total Spray Cost	\$1,296.00	\$400.00
Total Spare Part Cost	\$8,836.00	\$2,835.79
Total Other Cost	\$480.00	\$30.00
<b>TOTAL COST</b>	<b>\$11,119.00</b>	<b>\$3,465.79</b>
<b>Lump Sum Total</b>	<b>\$11,100.00</b>	<b>\$3,450.00 (L/S)</b>
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Ang Bang Kien	STEVE CHEN (LKK) / China Taiping
ARC / Surveyor Sign Off Date	11/11/2021 11:01 AM	10/11/2021 6:18 PM
Signature		
Remarks		L/S repair. take after spray

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2111-0285	<b>Invoice Number</b>	
<b>Quotation Date</b>	24.11.2021	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR FRONT RH PORTION	\$507.00	\$200.00
<b>Total Labour</b>	<b>\$507.00</b>	<b>\$200.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	\$378.00	\$200.00
TO RESPRAY FRONT BUMPER LOWER GRILLE	\$180.00	\$0.00
TO RESPRAY FRONT SUPPORT PANEL	\$180.00	\$0.00
TO RESPRAY FRONT FENDER RH	\$378.00	\$200.00
TO RESPRAY RIM	\$180.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,296.00</b>	<b>\$400.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$10.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	\$120.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$20.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$480.00</b>	<b>\$30.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		8121047020	LAMP ASSY, FOG, RH	1.00	\$910.20	10.00	\$819.18	Replace	Replace
		8118547691	UNIT , HEADLAMP , LH	0.00	\$2,558.90	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
		4355047020	HUB & BEARING ASSY, RH & LH	0.00	\$554.20	0.00	\$0.00	Replace	Not Given
		42611-47450	WHEEL, DISC FRONT	0.00	\$1,555.10	0.00	\$0.00	Replace	Not Given
		5387547070	LINER, FR FENDER, RH	0.00	\$198.40	0.00	\$0.00	Replace	Not Given
		7537447140	EMBLEM, SIDE PANEL (HYBRID)	1.00	\$52.90	25.00	\$39.68	Replace	Replace
		5380147080	FENDER SUB-ASSY, FR , RH	1.00	\$933.10	100.00	\$0.00	Replace	Repair
		5321347050	SUPPORT, RADIATOR UPPER RH	0.00	\$76.70	0.00	\$0.00	Replace	Not Given
		5320247901	SUPPORT S/A RH	0.00	\$237.00	0.00	\$0.00	Replace	Not Given
		5320547900	SUPPORT S/A UPPER,	0.00	\$364.90	0.00	\$0.00	Replace	Not Given
		8101647690	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	0.00	\$486.40	0.00	\$0.00	Replace	Not Given
		8114547691	UNIT , HEADLAMP , RH	1.00	\$2,558.90	10.00	\$2,303.01	Replace	Replace
		5141047020	COVER ASSY, ENGINE UNDER CENTER SET	0.00	\$452.80	0.00	\$0.00	Replace	Not Given

✓ CUT  
 X NN  
 X NN  
 X NN  
 X NN  
 X NN  
 X NN  
 ✓ NEC  
 R  
 X NN  
 X NN  
 X NN  
 X NN  
 ✓ BR  
 X NN

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 26/11/2021

User ID : PohSuan

		5142047030	COVER ASSY, ENGINE	0.00	\$180.10	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, FRT & RR BUMPER	10.00	\$1.50	25.00	\$11.25	Replace	Replace
		5310147080	GRILLE SUB-ASSY	0.00	\$335.60	0.00	\$0.00	Replace	Not Given
		5311247240	GRILLE, RADIATOR	0.00	\$165.00	0.00	\$0.00	Replace	Not Given
		5339547040	SEAL, HOOD TO FR END	0.00	\$24.40	0.00	\$0.00	Replace	Not Given
		5261847090	ABSORBER, FR BUMPER LOWER	0.00	\$117.00	0.00	\$0.00	Replace	Not Given
		5210247020	EXTENSION SUB-ASSY, RH	0.00	\$116.30	0.00	\$0.00	Replace	Not Given
		5261147140	ABSORBER, FR BUMPER	0.00	\$70.30	0.00	\$0.00	Replace	Not Given
		5202147110	REINFORCEMENT FRONT UPPER	0.00	\$691.10	0.00	\$0.00	Replace	Not Given
		5212747907	COVER, FR BUMPER RH	0.00	\$28.10	0.00	\$0.00	Replace	Not Given
		5211547050	SUPPORT, FR BUMPER RH	0.00	\$76.90	0.00	\$0.00	Replace	Check
		5211947962	COVER, FR BUMPER	1.00	\$495.50	25.00	\$371.63	Replace	Replace
<b>Total</b>					<b>\$13,368.04</b>		<b>\$3,544.75</b>		

XNN  
✓ NEC  
X NN  
X NN  
XNN  
X NN  
X NN  
X NN  
X NN  
X NN  
X NN  
✓ BR

**Added Spare Parts / Material Usage After Surveyor Signed off**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
<b>Total</b>									

3,544.75  
-20%  
2835.80  
+ 200.00  
+ 430.00  
3,465.80

L/S \$3,450/-

