

AIG

Vehicle number	SLD1594H
Make / Model	NISSAN NOTE
Chassis number	JN1TAAE12Z0972252
Accident date	5-11-21
Reference	2111-04

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	460 528.00 / net
1	REAR BUMPER RETAINER RH	61.00 / nec
1	TAILLAMP RH	320.00 X SUC
1	REAR FENDER RH	1271.00 / net
1	REAR FENDER INNER SHIELD RH	64.00 / DES
1	REAR WHEEL HUB W BEARING RH	143.20 X SUC
1	REAR SHOCK ABSORBER RH	133.00 X SUC
		2520.20
	Less 10%	252.02
		2268.18
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	RIM	500.00 X SUC
1	TYRE	400.00 X SUC
1 SET	REAR BUMPER CLIP	30.00 / nec
1 SET	REAR FENDER INNER SHIELD CLIP	30.00 / nec
	Subtotal	960.00
	Balance C/F	3228.18
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	150.00 20
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	200.00 XNW
3	REMOVE AND REFIT UNDERCARRIAGE	200.00 XWN
4	REMOVE AND REFIT REVERSE SENSOR	150.00 30
5	PANEL BEATING ON AFFECTED AREAS	800.00 400
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 400
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
	Subtotal	2450.00
	Grand total	5678.18

check price

Thuvan @ chhau to . com
 82235769
 1/5 after repair photo
 9/11/21 1730
 3 days wp

LKK Auto Consultants hence n
 the Repairer of the following:

- To resurvey before/after spray paint
- To display damaged part(s) during re
- Parts prices are subject to confirma
- Third party survey is on a "Without
- No illegal modification(s) is allowe
- Supplementary item(s) must be re
- is subject to final approval from In

Acknowledged by Repairer
 Signature:
 Date: