

AIG

Vehicle number	SLD1594H
Make / Model	NISSAN NOTE
Chassis number	JN1TAAE12Z0972252
Accident date	5-11-21
Reference	2111-04

Qty	Particulars	Unit Price - SGD \$
<u>PARTS REPLACEMENT - LIST ITEMS</u>		
1	REAR BUMPER	460 528.00 <i>net</i>
1	REAR BUMPER RETAINER RH	61.00 <i>net</i>
1	TAILLAMP RH	320.00 <i>xSuc</i>
1	REAR FENDER RH	<i>911</i> → 1271.00 <i>net</i>
1	REAR FENDER INNER SHIELD RH	64.00 <i>net</i>
1	REAR WHEEL HUB W BEARING RH	143.20 <i>xSuc</i>
1	REAR SHOCK ABSORBER RH	133.00 <i>xSuc</i>
		2520.20
	Less 10%	252.02
		2268.18
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>		
1	RIM	500.00 <i>xSuc</i>
1	TYRE	400.00 <i>xSuc</i>
1 SET	REAR BUMPER CLIP	30.00 <i>net</i>
1 SET	REAR FENDER INNER SHIELD CLIP	30.00 <i>net</i>
	Subtotal	960.00
	Balance C/F	3228.18
<u>LABOUR AND MISCELLANEOUS CHARGES</u>		
1	CHECK WIRING AND LIGHTNING SYSTEM	150.00 <i>20</i>
2	COMPUTERIZE AND CHECK WHEEL ALIGNMENT	200.00 <i>xNW</i>
3	REMOVE AND REFIT UNDERCARRIAGE	200.00 <i>xWN</i>
4	REMOVE AND REFIT REVERSE SENSOR	150.00 <i>30</i>
5	PANEL BEATING ON AFFECTED AREAS	800.00 <i>400</i>
6	SPRAY PAINTING ON AFFECTED AREAS	800.00 <i>400</i>
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 <i>30</i>
	Subtotal	2450.00
	Grand total	5678.18

Theravan @ chhauto.com
 82235769
 1/5 after repair photo
 9/11/21 1730
 3clays wP

1850

LKK Auto Consultants hence n
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during repair
- Parts prices are subject to confirmation
- Third party survey is on a "Without prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be repaired and is subject to final approval from Insured and Insurance Company

Acknowledged by Repairer
 Signature:
 Date: