

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **SLU 8753 E**
 Model : Nissan X-Trail
 Year : 2017
 Chassis No : JN1JANT32Z0010516

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Tailgate	1	\$ 4,258.00	\$ 4,258.00
2	Tailgate logo	1	\$ 286.30	\$ 286.30
3	Tailgate emblem 'X-Trail'	1	\$ 201.40	\$ 201.40
4	Tailgate weatherstrip	1	\$ 418.40	\$ 418.40
5	Tailgate windscreen moulding	1	\$ 285.70	\$ 285.70
6	Rear bumper	1	\$ 990.80	\$ 990.80
7	Rear bumper outer chrome moulding	1	\$ 244.00	\$ 244.00
9	Rear bumper side retainer	2	\$ 33.00	\$ 66.00
10	Rear bumper centre garnish	1	\$ 85.60	\$ 85.60
11	Rear bumper bracket	2	\$ 198.80	\$ 397.60
12	Rear bumper reinforcement	1	\$ 893.40	\$ 893.40
13	Rear bumper reinforcement bracket RH 1	2	\$ 367.10	\$ 734.20
14	Rear bumper reflector RH	1	\$ 286.30	\$ 286.30
15	Rear end panel	1	\$ 781.10	\$ 781.10
16	Rear end panel top garnish	1	\$ 183.50	\$ 183.50
17	Rear fender RH	1	\$ 1,426.10	\$ 1,426.10
18	Rear fender arch garnish RH	1	\$ 325.00	\$ 325.00
19	Rear fender air vents RH	1	\$ 78.90	\$ 78.90
20	Rear fender inner trim board RH	1	\$ 580.40	\$ 580.40

DDV
 } NECV
 NDX
 NECV
 BRV
 BRV
 NECV
 NSX
 BTXR
 BTX
 CRAV
 BRV
 NDX
 NDX
 CUTXR
 } NDX

Survey Resurvey
 9/11/2021 11/11/2021
 1315 hrs 1130 hrs

Parts Sub Total : \$ 12,816.70
 Discount : \$ 1,281.67
PARTS TOTAL : \$ 11,535.03

6446.70
 @ 10% 644.67
 5802.03

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Tailgate windscreen clips	1	\$ 50.00	\$ 50.00
3	Tailgate windscreen sealant	1	\$ 100.00	\$ <u>30.00</u> 100.00
4	Tailgate windscreen inner seal	1	\$ 100.00	\$ <u>30.00</u> 100.00
5	Tailgate windscreen primer and cleaner	1	\$ 80.00	\$ 80.00
6	Rear bumper clips	1	\$ 50.00	\$ <u>30.00</u> 50.00
7	Rear bumper outer chrome moulding clips	1	\$ 50.00	\$ 50.00
8	Rear bumper outer garnish clips	1	\$ 50.00	\$ 50.00
9	Rear bumper reverse sensor	2	\$ 250.00	\$ <u>200.00</u> 500.00
10	Rear end panel sealant	1	\$ 100.00	\$ 100.00
11	Rear end panel top garnish clips	1	\$ 50.00	\$ 50.00
12	Rear fender sealant	1	\$ 100.00	\$ 100.00
13	Rear fender inner cowl clips	1	\$ 50.00	\$ 50.00
14	Rear fender arch garnish clips	1	\$ 50.00	\$ 50.00
15	Rear fender inner trim board clips	1	\$ 50.00	\$ 50.00
16	Rear number plate w/casing	1	\$ 80.00	\$ <u>30.00</u> 80.00
SPECIAL NETT TOTAL :				\$ <u>320.00</u> 1,540.00

NNX
NNX
NECV
NECV
NNX
NECV
NNX
NSX
SCV
NNX
NNX
NNX
BR

Nos.	LABOUR	S\$
1	R&R tailgate component	\$ <u>80.00</u> 150.00
2	R&R tailgate windscreen	\$ <u>120.00</u> 250.00
3	R&R rear bumper reverse sensor	\$ <u>60.00</u> 100.00
4	Check wiring	\$ 100.00
5	Uphostery	\$ 300.00
6	Panel beating	\$ <u>600.00</u> 1,600.00
7	Rust proofing	\$ 200.00
8	Spray painting	\$ <u>600.00</u> 1,600.00
LABOUR TOTAL :		\$ <u>1460.00</u> 4,300.00

Lump sum repair
Repair days 5

PARTS TOTAL : \$ 11,535.03
SPECIAL NETT TOTAL : \$ 1,540.00
LABOUR TOTAL : \$ 4,300.00
GRAND TOTAL : \$ 17,375.03

Parts 5802.03
SN 320.00
Labour 1460.00
7582.03
@ 20% 1516.41
6065.62

LS 6050/2

TGum Min
14/11/2021

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: