

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 10 Dec 2021

**Preliminary Advice**

Insured Vehicle No : SFR4690R  
TP Vehicle No : SJU9121X  
Make : MAZDA MX-5  
Date of Inspection : 09/11/2021  
Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)  
8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT  
SINGAPORE 415875

Accident Date : 07/11/2021  
Assignment Date : 10/12/2021  
Est. Duration of Repair : 9

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,646.34
Revised Amount	:S\$	8,526.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	8,526.56

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.