

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com; cs-a@lkkauto.com; admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21011457/TPA3Q2**Date:** 17/07/2023**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480420
Claimant Vehicle No :	SMR228L	Insured Vehicle No :	SFB887B
Date of Loss:	06/11/2021	Nature of Claim:	TP
		Claim No:	2714833478SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMR228L		
Make & Model:	PORSCHE 911, CARRERA 4	Engine No:	M960569604843
Reg. Date:	17/03/2006 (Man. Year: 2006)	Chassis No:	WP0ZZZ99Z6S701288
Colour:	Orange	Odometer:	88938 km
Engine Capacity:	3596 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	305/30 R19	Rear Tyre Size:	305/30 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,502.58	12,687.72	36,814.86	74.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,550.00	1,670.00	5,880.00	77.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	57,052.58	14,357.72	42,694.86	74.83
Approved Total (Overridden) (S\$)		11,450.00		
Nett Amount (S\$)	57,052.58	11,450.00	45,602.58	79.93
+ Car Rental (7.0 x S\$150.00/day + 7.00% GST) (S\$)		1,123.50		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		12,580.95		
Global Sum Settlement (S\$)		12,500.00		

INSPECTION

Date of Assignment:	09/11/2021	
Date Inspected:	10/11/2021	Inspected At: J.E.W MOTORS PTE LTD (HQ) 60 Jalan Lam Huat Carros Centre #03-72 Singapore 737869
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	5,129.00 FL	*3,966.00 FL
2	1		*REAR BOOTLID TOP VENT LID	Not Necessary	4,193.00 FL	*- FL
3	1		*REAR BOOTLID EMBLEM PORSCHE	Necessary	315.00 FL	*195.00 FL
4	1		*REAR BOOTLID EMBLEM 911	Necessary	301.00 FL	*170.00 FL
5	1		*REAR BOOTLID EMBLEM CARRERA	Necessary	345.00 FL	*205.00 FL
6	2		*REAR BOOTLID DAMPER L+R	Not Necessary	2,330.00 FL	*- FL
7	2		*REAR BOOTLID HINGE MECHANISM CENTER L+R	Not Necessary	3,350.00 FL	*- FL
8	2		*REAR BOOTLID HINGE MECHANISM SIDE L+R	Not Necessary	2,354.00 FL	*- FL
9	1		*REAR BOOTLID INNER TRIM	Not Necessary	125.00 FL	*- FL
10	1		*REAR BOOTLID AIR INTAKE TOP	Not Necessary	1,003.00 FL	*- FL
11	1		*REAR BOOTLID AIR INTAKE BOTTOM HOSE	Not Necessary	952.00 FL	*- FL
12	1		*REAR BOOTLID FAN COWLING	Cracked	1,498.00 FL	*1,498.00 FL
13	1		*REAR BOOTLID FAN BLADE	Not Necessary	1,955.00 FL	*- FL
14	1		*REAR BOOTLID FAN MOTOR	Not Necessary	1,565.00 FL	*- FL
15	1		*REAR BOOTLID CATCH	Not Necessary	174.00 FL	*- FL
16	1		*REAR BOOTLID LOCK MECHANISM	Not Necessary	678.00 FL	*- FL
17	1		*REAR BOOTLID WEATHERSTRIP	Not Necessary	512.00 FL	*- FL
18	1		*REAR TAILLAMP L+R	N/S Not Necessary /O/S Cut	1,040.00 FL	*520.00 FL
19	2		*REAR TAILLAMP PANEL L+R	Not Necessary	1,840.00 FL	*- FL
20	1		*REAR BUMPER	Cracked	2,501.80 FL	*2,501.80 FL
21	2		*REAR BUMPER RETAINER L+R	Cracked	508.00 FL	*508.00 FL
22	2		*REAR BUMPER RETAINER SMALL L+R	Not Necessary	398.00 FL	*- FL
23	1		*REAR BUMPER SPONGE	Not Necessary	561.00 FL	*- FL
24	1		*REAR BUMPER REINFORCEMENT BAR	Bent	1,541.00 FL	*1,541.00 FL
25	2		*REAR BUMPER BRACKET L+R	Not Necessary	1,024.00 FL	*- FL
26	2		*REAR BUMPER REVERSE SENSOR L+R	Not Necessary	1,304.00 FL	*- FL
27	2		*REAR BUMPER VRN LAMP L+R	Cracked	420.00 FL	*420.00 FL
28	1		*REAR BUMPER REVERSE CAMERA	Distorted	1,145.00 FL	*1,145.00 FL
29	1		*REAR END PANEL	Bent	842.67 FL	*842.67 FL
30	1		*REAR END PANEL ENGINE COVER	Not Necessary	951.00 FL	*- FL
31	2		*REAR EXHAUST L+R	Not Necessary	4,082.00 FL	*- FL
32	2		*REAR EXHAUST CHROME TIP L+R	Not Necessary	956.40 FL	*- FL
33	1		*REAR EXHAUST HEATSHIELD	Bent	1,001.00 FL	*485.00 FL
34	2		*REAR EXHAUST MANIFOLD L+R	Not Necessary	7,508.00 FL	*- FL
35	10		*REAR BOOTLID INNER TRIM CLIPS	Not Necessary	100.00 FS	*- FS
36	10		*REAR TAILLAMP CLIPS	Necessary	100.00 FS	*20.00 FS
37	10		*REAR BUMPER CLIPS	Necessary	100.00 FS	*30.00 FS
38	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*40.00 FS
39	1		*REAR TAILLAMP PANEL SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 54,942.87 14,087.47
- List Item Discount on L Items 10.00/10.00% (\$\$) 5,440.29 1,399.75

Total Parts (\$\$) 49,502.58 12,687.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ON AFFECTED AREAS	New	1,800.00	700.00
2	SPRAY PAINT ON AFFECTED AREAS	New	1,800.00	700.00
3	TO RNR REAR EXHAUST	New	400.00	0.00
4	TO CHECK WIRING AND TAIL LAMP FUNCTION	New	150.00	30.00
5	TO RNR REAR INNER TRIM AND UPHOLSTERY	New	400.00	60.00
6	TO CHECK WATER LEAK	New	300.00	0.00
7	TO PERFORM DIAGNOSTIC AND CLEAR FAULTS	New	600.00	0.00
8	TO RNR REAR TAILGATE MECHANISM	New	400.00	60.00
9	TO RNR REAR REVERSE SENSOR AND CHECK FUNCTION	New	300.00	30.00
10	TO PERFORM RUST PROOFING	New	200.00	30.00
11	TO RNR REAR BOOTLID REAR VENT LID AND CHECK FUNCTION }	New	400.00	60.00
12	TO RNR REAR BOOTLID FAN AND CHECK FUNCTION }	New	400.00	0.00
13	TO CHECK AND ENSURE NO OVERHEATING ON ENGINE	New	400.00	0.00
Gross Labour Cost (S\$)			7,550.00	1,670.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >