

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS3/CTI21011458/Vuy3	
	3 ANSON ROAD # SPRINGLEAF TOV		Date:	09/11/2021		
				Code:	СТІ	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBB 9452K	Veh. Inspected		SMK 3171H	
	Policy No.	DMCVSNA00059562100	Coverage (\$)		0.00	
	Claim No.	SNM21D206423/C02/GBB9452 K/TANKL	Excess (\$)		0.00	
	Assign From	TAN KAH LEONG	Assign Date		09/11/2021	
2.	2. Vehicle Particulars & Condition					
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	05/11/2021	Inspection Date	е	10/11/2021	
	Survey held at	urvey held at SPEEDWERKZ PTE LTD				
		13 KAKI BUKIT ROAD 4, #01-20, BARTLEY BIZ CENTRE, SINGAPORE 417807				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					